



report date: 2024-03-28

General information

Make	JAGUAR
Model	XK CONVERTIBLE
Colour	Grey
Year of manufacture	2006
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	294 BHP
Max. torque	411 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	33.6 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-10-28
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-14
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	39
Total items failed	2

MOT #17	2023-12-15 10:10
MOT test number	301370832555
Result	✓ Passed
Next expiry date	2024-12-14

MOT #16	2022-12-14 18:23
MOT test number	156938697448
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2021-09-29 13:42
MOT test number	122864572186
Result	✓ Passed

MOT #14	2020-09-28 09:14
MOT test number	655170005054
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #13

2019-10-18 10:28

MOT test number

744759213549

Result

✓ Passed

- Advice

Rear exhaust heat shield adrift
- Advice

Warning light on for pedestrian system
- Advice

Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Offside Rear tyre down to 3mm
- Advice

Front no. plate light cracks
- Advice

Head lamp lenses glazed (slight)
- Advice

Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Rear shock absorber lower bush worn
- Advice

Offside Rear Lower arm, bush has a split gaiter

**MOT #12** 2019-10-17 15:23**MOT test number** 140433458680**Result** ✗ Failed**MAJOR** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Advice** Rear exhaust heat shield adrift**DANGEROUS** Offside Front Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))**Advice** Warning light on for pedestrian system**Advice** Offside Rear tyre down to 3mm**Advice** Front no. plate light cracks**Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Head lamp lenses glazed (slight)**Advice** Offside Rear shock absorber lower bush worn**Advice** Offside Rear Lower arm, bush has a split gaiter**MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #11** 2018-10-22 13:43**MOT test number** 943749500395**Result** ✓ Passed**MOT #10** 2017-09-20 13:59**MOT test number** 925635955816**Result** ✓ Passed

**MOT #9** 2017-09-18 10:58**MOT test number** 987168058444**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Headlamp not working on main beam (1.7.5a)**MOT #8** 2016-10-21 14:41**MOT test number** 894660701292**Result** ✓ Passed**MOT #7** 2015-10-14 07:53**MOT test number** 455247120037**Result** ✓ Passed**Advice** Undertrays fitted not allowing full inspection of components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Front Inner Tyre worn close to the legal limit 245/45R18 (4.1.E.1)**Advice** Engine covers fitted not allowing full inspection of components**Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**MOT #6** 2014-10-20 08:54**MOT test number** 979243394211**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-11-01 09:43**MOT test number** 779105403390**Result** ✓ Passed**MOT #4** 2012-10-01 15:13**MOT test number** 555995572202**Result** ✓ Passed**Notice** Nearside rear tyre has gouges in outer sidewall**Notice** Rear wheels scuffed (couldnt see any cracks)**MOT #3** 2011-10-27 12:23**MOT test number** 757320601344**Result** ✓ Passed**MOT #2** 2010-10-12 12:39**MOT test number** 644905080217**Result** ✓ Passed**Notice** Nearside rear tyre has gouges and cuts to outer sidewall**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside front tyre has small gouges to outer sidewall**MOT #1** 2009-10-19 15:35**MOT test number** 204162599297**Result** ✓ Passed**Notice** Nearside rear tyre has small gouges in outer wall**Notice** Nearside rear tyre down to 2.7mm



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 December 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	GK56XKG
Plate since	2019-09-29
Current registration	GK56XKG
Plate since	2019-09-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-10-27
Last registration	2023-12-15
Complete history	See info



Registration #1	2006-10-27	29 mi
Registration #2	2009-10-19	13.562 mi
Registration #3	2010-10-12	17.967 mi
Registration #4	2011-10-27	23.583 mi
Registration #5	2012-10-01	26.989 mi
Registration #6	2013-11-01	31.691 mi
Registration #7	2014-10-20	36.487 mi
Registration #8	2015-10-14	39.726 mi
Registration #9	2016-10-21	43.132 mi
Registration #10	2017-09-18	46.549 mi
Registration #11	2018-09-20	50.000 mi
Registration #12	2019-09-20	53.500 mi
Registration #13	2020-09-20	57.000 mi
Registration #14	2021-09-20	60.500 mi
Registration #15	2022-09-20	64.000 mi
Registration #16	2023-09-20	67.500 mi
Registration #17	2024-09-20	71.000 mi
Registration #18	2025-09-20	74.500 mi
Registration #19	2026-09-20	78.000 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1815 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	06032910285G