



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 MPI SE
Colour	White
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-22
Pictures	23
Listing price	View report



source: [yesauto.com](#)

**MOT history**

MOT expiry date	2025-03-01
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #7	2024-03-02 08:41
MOT test number	859243906840
Result	✓ Passed
Next expiry date	2025-03-01

MOT #6	2023-02-28 15:38
MOT test number	508874192716
Result	✓ Passed

MOT #5	2023-02-27 16:54
MOT test number	744589532003
Result	✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin near lower limit (1.1.13 (a) (ii))

MOT #4	2022-02-25 16:59
MOT test number	583941993063
Result	✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing 195/55/16 87H (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2021-02-17 17:22**MOT test number** 268215011961**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))**MOT #2** 2020-02-11 11:47**MOT test number** 223854686185**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing perishing side walls (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perishing side walls (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing perishing side walls (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perishing side walls (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge TYRE WORN TO LEGAL LIMIT (5.2.3 (e))**MOT #1** 2019-03-01 08:30**MOT test number** 344692229386**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 March 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-02
Last registration	2024-03-02
Complete history	See info



Registration #1	2016-03-02	19 mi
Registration #2	2019-03-01	14.133 mi
Registration #3	2020-02-11	21.072 mi
Registration #4	2021-03-01	21.072 mi
Registration #5	2022-03-01	21.072 mi
Registration #6	2023-03-01	21.072 mi
Registration #7	2024-03-01	21.072 mi
Registration #8	2025-03-01	21.072 mi
Registration #9	2026-03-01	21.072 mi
Registration #10	2027-03-01	21.072 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1449 mm
Length	4049 mm
Wheel base	2570 mm
Kerb weight	1158 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	G4LAGM927120