





report date: 2024-03-29

General information

Make	AUDI
Model	ALLROAD TDI ALLROAD TDV QUATTRO
Colour	Silver
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	380 Nm at 1.400 rpm
Engine capacity	2.698 сс
Cylinders	6
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.5 mpg
CO2 emission	230 g/km
CO2 label	L



CarCheck.co.uk page 1/12



NUO8UGN report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-13

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2023-02-09
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	16
Total items failed	12

MOT #17	2022-01-29 08:46
MOT test number	516040636968
Result	✓ Passed
Next expiry date	2023-02-09

MOT #16		2021-02-10 12:44
MOT test	number	369971124457
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner and outer edge	es (5.2.3 (e))
Advice	Rear Tyre worn close to legal limit/worn on edge Both (inner edges) (5.2.3 (e)))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	

MOT #15	2021-02-03 13:48
MOT test number	785649556852
Result	× Failed
Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice Rear Tyre worn close to legal limit/worn on edge Both (inner edges) (5.2.3 (e))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge inner and outer edge	s (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-29

 MOT #14
 2019-06-14 13:09

 MOT test number
 706778103447

 Result
 ✓ Passed

 MOT #13
 2018-06-08 14:21

 MOT test number
 171047877323

 Result
 ✓ Passed

 Advice
 Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

MOT test number

627870643867

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #10

MOT test number

736472996348

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #9

MOT test number

Fesult

Advice

Offside Rear slight damage to outer tyre wall

 MOT #8
 2015-07-17 15:45

 MOT test number
 238748295446

 Result
 ✓ Passed

MOT #7 2015-07-16 15:32 MOT test number 427737895172

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2014-06-21 10:16

MOT test number 239032274426

Notice Both front tyres heavily worn on edges

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #5

MOT test number

607591274111

Result

Kesult

Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)

Notice

Both front tyres heavily worn on edges

MOT #4 2013-07-12 09:59 **MOT** test number 647783393150 Result ✓ Passed **MOT** #3 2013-07-12 09:59 119093193129 **MOT test number** Result × Failed **Pass with rectification** Offside Headlamp aim too low (1.8) **Pass with rectification** Nearside Headlamp aim too low (1.8)

MOT #2

MOT test number

286016282168

Result

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

 MOT #1
 2011-03-25 11:26

 MOT test number
 515994781014

 Result
 ✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	history
-------	---------

For how long did the current and previous owner(s) have this AUDI? How many owners did Check it in the premium report and see all owner registrations. Download the full report \underline{h}		ve?

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	NK NEW	
Plate since		
Current registration	NK NY	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-29
Last registration	2022-01-29
Complete history	See info



Registration #1	2008-03-29	6 mi
Registration #2	2011-03-25	25.368 mi
Registration #3	2012-07-04	31.500 mi
Registration #4	2013-07-12	53.024 mi
Registration #5	2014-06-20	77.219 mi
Registration #6	2014-06-21	77.219 mi
Registration #7	2015-07-16	108.720 mi
Registration #8	2015-07-17	108.720 mi
Registration #9	2016-07-07	132.943 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1862 mm
Height	1519 mm
Length	4934 mm
Wheel base	2833 mm
Kerb weight	1875 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	80 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number BPP 131145