





report date: 2024-03-29

General information

Make	ТОУОТА
Model	COROLLA VERSO D-4D T SPIRIT
Colour	Black
Year of manufacture	2005
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	280 Nm at 2.000 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

		1
ᆮ	HLIV	-

Date	2021-10-14
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-05-29
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	34
Total items failed	10

MOT #22		2023-05-10 16:19
MOT test	number	702109741265
Result		✓ Passed
Next expi	ry date	2024-05-29
Advice	Front Tyre worn close to legal limit/worn on edge Both front tyres (5.2.3	3 (e))
Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arm bushes worn (5.3.4 (a) (i))		
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, but not excessively Both front (1.1.14 (a) (i))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #21 2023-05-09 19:29

MOT test number 550447299153

Result × Failed

MAJOR Offside Front Driver's door cannot be opened from inside the vehicle (6.2.3 (a))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arm bushes worn (5.3.4 (a) (i))

Advice Front Brake disc worn, but not excessively Both front (1.1.14 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both front tyres (5.2.3 (e))

Pass with rectification Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

MOT #20 2022-05-30 11:14

MOT test number 835467987797

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19 2022-05-30 11:14

MOT test number 573472238665

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #18	2020-12-02 12:30
MOT test number	922893587751
Result	✓ Passed
MOT #17	2019-06-06 12:17
MOT test number	421225373407
Result	✓ Passed
MOT #16	2019-06-06 12:17
MOT test number	154998630261
Result	× Failed
Pass with rectification Driver's airbag obviously inoperative (7.1.5 (c))	

Pass with rectification Driver's airbag obviously inoperative (7.1.5 (c))	
MOT #15	2018-05-31 11:
MOT test number	1400767137
Result	✓ Pass
MOT #14	2017-06-09 10:
MOT test number	1413702000
Result	✓ Pass

	✓ Passed
	2016-05-26 13:35
number	352708062928
	✓ Passed
Advice tracking	
O/s front tyre perish	
Nearside Rear tyre perish	
Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
N/s front tyre perish	
	Advice tracking O/s front tyre perish Nearside Rear tyre perish Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/14



O/s front tyre perish

Advice

LC05WGD

report date: 2024-03-29

MOT #12 2016-05-26 08:43 **MOT** test number 398716757928 Result × Failed Fail Nearside Headlamp aim too low (1.8) Advice N/s front tyre perish **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Advice tracking Fail Offside Stop lamp not working (1.2.1b) Fail Offside Headlamp aim too low (1.8)

 MOT #11
 2015-05-14 10:28

 MOT test number
 217004135436

 Result
 ✓ Passed

MOT #10 2014-05-12 09:51
MOT test number 297052934179
Result ✓ Passed

MOT #9 2013-05-22 10:39

MOT test number 198402343176

Result

Passed

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #8 2012-05-29 09:43

MOT test number 828190352154

MOT #7 2012-05-24 11:40

MOT test number 986355942111

Result X Failed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Fail Nearside brake disc in such a condition that it is seriously weakened (3.5.1i)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2011-05-23 10:19

MOT test number 139423441168

MOT #5 2011-05-20 12:36

MOT test number 586560041108

Result X Failed

Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3)

MOT #4 2010-05-20 10:10

MOT test number 494150940187

Result
✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #3

MOT test number

Result

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2

MOT test number

S44885639145

Result

✓ Passed

MOT test number

2008-05-29 14:53

MOT test number

223530258460

Result

✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full		

	More info >	
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK NEW TOTAL	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 11/14



LC05WGD report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-05-27
Last registration	2023-05-10
Complete history	See info



Registration #1	2005-05-27	16 mi
Registration #2	2008-05-29	14.275 mi
Registration #3	2009-05-15	17.618 mi
Registration #4	2010-05-19	21.423 mi
Registration #5	2010-05-20	21.424 mi
Registration #6	2011-05-20	23.184 mi
Registration #7	2011-05-23	23.186 mi
Registration #8	2012-05-24	25.446 mi
Registration #9	2012-05-29	25.446 mi
Registration #10	2013-05-22	27.627 mi
Registration #11	2014-05-12	30.760 mi
Registration #12	2015-05-14	33.326 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		11.777 esi
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 au

More info >



LC05WGD
report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles 2

Engine number 1CD0475943