



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D3 SE
Colour	Black
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-12-23
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-26
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #12	2024-02-27 13:12
MOT test number	525566725931
Result	✓ Passed
Next expiry date	2025-02-26
Advice	Under trays fitted

MOT #11	2023-01-05 16:35
MOT test number	582338016219
Result	✓ Passed

MOT #10	2021-08-05 12:43
MOT test number	931249498665
Result	✓ Passed
Advice	Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9	2020-08-06 13:26
MOT test number	348544605537
Result	✓ Passed

**MOT #8** 2019-08-05 13:46**MOT test number** 386720143015**Result** ✓ Passed**MOT #7** 2018-08-09 12:42**MOT test number** 715663750309**Result** ✓ Passed**Advice** Engine cover/under tray fitted obstructing some component check.**MOT #6** 2017-08-10 13:44**MOT test number** 602387695842**Result** ✓ Passed**MOT #5** 2017-08-10 11:25**MOT test number** 163019092618**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2016-05-25 09:40**MOT test number** 144102817170**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #3	2015-05-29 13:34
MOT test number	156269445172
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #2	2014-05-02 13:30
MOT test number	388992724198
Result	✓ Passed

MOT #1	2013-11-05 14:15
MOT test number	269089903369
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
26 February 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-11-25
Last registration	2024-02-27
Complete history	See info



Registration #1	2010-11-25	8 mi
Registration #2	2013-11-05	26.026 mi
Registration #3	2014-05-02	29.376 mi
Registration #4	2015-05-29	36.681 mi
Registration #5	2016-05-25	48.832 mi
Registration #6	2017-08-10	69.656 mi
Registration #7	2017-08-10	69.656 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1684 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	882769