





report date: 2024-03-29

General information

Make	NISSAN
Model	NOTE ACENTA PREMIUM
Colour	Grey
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-02

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

$M \cap T$	hictory
	history

MOT expiry date	2024-07-13
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	7
Total items failed	5

MOT #6	2023-07-14 09:48
MOT test number	151838615958
Result	✓ Passed
Next expiry date	2024-07-13
Advice Items removed from driver's view prior to test Mirror hanger	

MOT #5	2022-07-05 11:16
MOT test number	546334381984
Result	✓ Passed
MOT #4	2021-07-13 08:57
MOT test number	499173327676
Result	✓ Passed
MOT #3	2020-12-15 11:33
MOT test number	307623365751
Result	✓ Passed

MOT #2	2020-02-25 14:21
MOT test number	146746697840
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2020-02-25 10:13

MOT test number 998969375656

Result X Failed

Minor Offside Front Tyre obviously under inflated (5.2.3 (I))

Fail Offside Front Tyre has ply or cords exposed under ply showing on inner and outer edges (5.2.3 (d) (ii))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Windscreen washer not working (3.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Tyre obviously under inflated (5.2.3 (I))

Fail
Nearside Front Tyre has ply or cords exposed under ply showing on inner and outer edges (5.2.3 (d) (ii))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Offside Windscreen washer not working (3.5 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



BD17KZP report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

BD17KZP

report date: 2024-03-29

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report here. More info

Plate changes

See in this check if this NISSAN had different number plates.

More info >

CarCheck.co.uk page 8/11



BD17KZP report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-31
Last registration	2023-07-14
Complete history	See info



Registration #1	2017-03-31	29 mi
Registration #2	2020-02-25	22.563 mi
Registration #3	2020-02-25	22.564 mi
Registration #4	2020-12-15	24.862 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 10/11



BD17KZP report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	***
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1040 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/

Engine number

124627R