




report date: 2024-03-29

General information

Make	FORD
Model	RANGER WILDTRAK 4X4 DCB TDCI
Colour	Orange
Year of manufacture	2016
Gearbox	6 speed automatic

Engine & fuel consumption

Power	198 BHP
Engine capacity	3.198 cc
Cylinders	5
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	265 g/km
CO2 label	M






Internet history

Entry 3

Date	2022-09-01
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 2

Date	2021-09-15
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-29
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2024-11-02
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	0

MOT #7	2023-11-03 09:53
MOT test number	847148969051
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2022-10-04 14:00
MOT test number	782225611071
Result	✓ Passed

MOT #5	2022-10-03 10:47
MOT test number	506244601435
Result	✗ Failed
MAJOR	Offside Headlamp aim too low (4.1.2 (a))
MAJOR	Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #4	2021-10-19 15:19
MOT test number	649746759971
Result	✓ Passed

**MOT #3** 2021-10-14 10:42**MOT test number** 723384058460**Result** ✗ Failed**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**DANGEROUS** Offside Rear Valve stem seriously damaged Multiple deep cuts (5.2.3 (j))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge low tread on inner edge (5.2.3 (e))**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Valve stem slightly damaged Small cuts (5.2.3 (j))**MOT #2** 2020-11-03 11:16**MOT test number** 619003927984**Result** ✓ Passed**Advice** Engine undertrays fitted obscuring testable items**Advice** Engine covers fitted obscuring testable items**MOT #1** 2019-08-19 18:43**MOT test number** 309675002130**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
2 November 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	2 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>VO16MVM</b>
Plate since	2019-09-29
Current registration	<b>VO16MVM</b>
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-16
Last registration	2023-11-03
Complete history	<a href="#">See info</a>



Registration #1	2016-03-16	12 mi
Registration #2	2019-08-19	26.465 mi
Registration #3	2020-11-03	41.079 mi
Registration #4	2020-05-20	35.377 mi
Registration #5	2020-05-20	35.377 mi
Registration #6	2021-10-14	52.175 mi
Registration #7	2020-05-20	35.377 mi
Registration #8	2020-05-20	35.377 mi
Registration #9	2020-05-20	35.377 mi
Registration #10	2020-05-20	35.377 mi
Registration #11	2020-05-20	35.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	86%
Pedestrian	81%
Safety systems	71%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2163 mm
Height	1815 mm
Length	5362 mm
Kerb weight	2083 kg
Max. allowed weight	3200 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	FJ17839