



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI XTR
Colour	Blue
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-08
Pictures	36
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-17
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	10
Total items failed	10

MOT #16	2023-07-18 15:18
MOT test number	273516658069
Result	✓ Passed
Next expiry date	2024-07-17

MOT #15	2023-07-17 12:52
MOT test number	184228802623
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #14	2022-07-01 12:57
MOT test number	453321216221
Result	✓ Passed

MOT #13	2022-07-01 10:31
MOT test number	618452594765
Result	✗ Failed
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12** 2021-06-18 10:40**MOT test number** 862588600889**Result** ✓ Passed**MOT #11** 2021-01-11 14:32**MOT test number** 885822934025**Result** ✓ Passed**MOT #10** 2021-01-11 11:12**MOT test number** 773396073911**Result** ✗ Failed**Fail** Front Brake disc in such a condition that it is seriously weakened both(inner surface) (1.1.14 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (2mm) (5.2.3 (e))**MOT #9** 2020-01-31 11:40**MOT test number** 304884925023**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened slight corrosion (1.1.14 (a) (ii))**Advice** Offside Rear lens cracked

**MOT #8** 2020-01-31 10:30**MOT test number** 852935738563**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Fail** Offside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened slight corrosion (1.1.14 (a) (ii))**Advice** Offside Rear lens cracked**MOT #7** 2019-01-28 09:40**MOT test number** 743585738215**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2018-01-12 15:49**MOT test number** 589135763841**Result** ✓ Passed**MOT #5** 2017-06-16 09:07**MOT test number** 189671203555**Result** ✓ Passed**MOT #4** 2016-06-01 08:36**MOT test number** 830368934277**Result** ✓ Passed**MOT #3** 2015-06-26 17:45**MOT test number** 456147475122**Result** ✓ Passed



MOT #2	2015-06-26 17:45
MOT test number	168407875178
Result	✗ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2014-06-03 11:11
MOT test number	716054454143
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
17 July 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-06-13
Last registration	2023-07-18
Complete history	See info



Registration #1	2011-06-13	28 mi
Registration #2	2014-06-03	11.932 mi
Registration #3	2015-06-26	20.873 mi
Registration #4	2016-06-01	26.262 mi
Registration #5	2017-06-16	31.141 mi
Registration #6	2018-01-12	32.647 mi
Registration #7	2019-01-28	39.626 mi
Registration #8	2020-01-31	46.085 mi
Registration #9	2020-01-31	46.085 mi
Registration #10	2020-01-31	46.085 mi
Registration #11	2020-01-31	46.085 mi
Registration #12	2020-01-31	46.085 mi
Registration #13	2020-01-31	46.085 mi
Registration #14	2020-01-31	46.085 mi
Registration #15	2020-01-31	46.085 mi
Registration #16	2020-01-31	46.085 mi
Registration #17	2020-01-31	46.085 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1426 kg
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBEV3007920