





report date: 2024-03-28

General information

Make	AUDI
Model	A3 MPI S LINE
Colour	Grey
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	41.5 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2021-01-27

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-01-27
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-26
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #13		2023-07-11 15:52
MOT test	number	850017866458
Result		✓ Passed
Next expi	ry date	2024-07-26
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both s	ides (1.1.14 (a) (ii))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i	i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #12		2022-07-27 14:05
MOT test i	number	525148620283
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (i))	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cord	ls inner wall (5.2.3 (d)
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

S10961562724

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #10
 2019-07-03 15:03

 MOT test number
 861574077382

 Result
 ✓ Passed

 MOT #9
 2019-07-02 14:16

 MOT test number
 280814626698

Fail Front Windscreen washer not working (3.5 (a))

Minor Brake fluid warning lamp illuminated (1.1.10 (f))

MOT #8

MOT test number

654599309815

Result

✓ Passed

MOT #7

MOT test number

189244621469

Result

Fail Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



Result

Notice

Notice

NA59TGF

report date: 2024-03-28

✓ Passed

MOT #6	2017-07-10 15:23
MOT test number	540281974516
Result	✓ Passed
MOT #5	2016-07-06 12:21
MOT test number	312944377503
Result	✓ Passed
MOT #4	2015-04-13 11:11
MOT test number	207413005107
Result	✓ Passed
MOT #3	2014-10-28 13:49
MOT test number	139521504307
Result	✓ Passed
Notice Engine covers fitted obscuring some components in the engine bay	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Under-trays fitted obscuring some underside components	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #2	2013-10-21 12:14
MOT test number	218304693219
Result	✓ Passed
	v i dosed
MOT #1	2012-10-22 11:44
MOT test number	237026492245

CarCheck.co.uk page 5/12

Upper engine covers fitted preventing full inspection of vehicle

Lower chassis covers fitted preventing full inspection of vehicle



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

\sim		ner	11-15		
-(-)	w/r	۱er	nı	СТ	nrν
\sim	V V I				\mathbf{v}

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SIL
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-27
Last registration	2023-07-11
Complete history	See info



Registration #1	2009-10-27	7 mi
Registration #2	2012-10-22	7.719 mi
Registration #3	2013-10-21	13.476 mi
Registration #4	2014-10-28	18.752 mi
Registration #5	2015-04-13	21.055 mi
Registration #6	2016-07-06	28.508 mi
Registration #7	2017-07-10	40.523 mi
Registration #8	2018-07-03	52.482 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionin
60295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4238 mm
Wheel base	2578 mm
Kerb weight	1185 kg
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number BSE 786266