





report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 35 L3 BLUEHDI
Colour	White
Year of manufacture	2018
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	42.8 mpg
CO2 emission	173 g/km
CO2 label	Н



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

Entry 1

Date 2022-07-26

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



BX68ACF report date: 2024-03-29

MOT history

MOT expiry date	2024-09-13
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	3
Total items failed	10

MOT #6	2023-09-14 10:00
MOT test number	198854833025
Result	✓ Passed
Next expiry date	2024-09-13

MOT #5		2023-09-14 10:00
MOT test number		381418412125
Result		X Failed
Pass with rectification	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #4	2023-07-24 10:04	
MOT test number	375343740082	
Result	× Failed	
Fail Offside Rear Rear fog lamp missing (4.5.1 (a) (ii))		
Advice Offside Front Tyre worn close to legal limit/worn	on edge (5.2.3 (e))	
Fail Offside Front Windscreen wiper does not clear the w	indscreen effectively (3.4 (b) (ii))	
Fail Nearside Rear Outline marker lamp missing badly damaged (4.2.1 (a) (ii))		
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))		
Fail Nearside Rear Brake cable damaged missing (1.1.15	(a))	

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT #3

MOT test number

Result

MOT #2

MOT test number

2021-10-28 11:01

MOT test number

210860108893

Result

Advice

Offside wing damaged and catching door when opening

MOT test number

Result

Advice Offside wing damaged and catching door when opening

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

CarCheck.co.uk page 4/10



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/10



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

HARMAN AND AND AND AND AND AND AND AND AND A	

	More info >
Plate changes See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	IIK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 7/10



BX68ACF report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-10-23
Last registration	2023-09-14
Complete history	See info



Registration #1	2018-10-23	15 mi
Registration #2	2021-10-21	15.325 mi
Registration #3	2021-10-28	15.325 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 9/10



BX68ACF report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2770 mm
Height	2153 mm
Length	5843 mm
Kerb weight	1655 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Number of axles	2
Engine number	DYZZ4173487

CarCheck.co.uk page 10/10