






General information

Make	MERCEDES-BENZ	
Model	CLA CLA220 CDI AMG SPORT	
Colour Red		
Year of manufacture 2014		
Top speed	143 mph	
0 - 100 km/h	8.2 seconds	
0 - 60 mph	8.2 seconds	
Gearbox	7 speed automatic	

Engine & fuel consumption

Power	125 kW / 170 HP / 170 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	111 g/km
CO2 label	С







Internet history

Entry 4

Date


2023-02-14

5

Pictures

Listing price

View report




source: autotrader.co.uk

Entry 3	
Date	2022-12-20
Pictures	5
Listing price	View report



source: autotrader.co.uk

Entry 2	
Date	2021-12-23
Pictures	5
Listing price	View report



source: autotrader.co.uk

Entry 1 Date CarCheck.co.uk

2021-10-10

Pictures

Listing price

5

View report





source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-13
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #8	2023-12-21 16:51
MOT test number	127825676945
Result	Passed
Next expiry date	2025-01-13
Advice Nearside Rear wear on inner edge	

MOT #7	2023-01-14 14:29
MOT test number	819204492722
Result	✓ Passed
Advice Front Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

МОТ #6			2023-01-14 14:29
MOT test number	r		435031297431
Result			🗙 Failed
Pass with rectif	fication	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Front In	nner Tyre	worn close to legal limit/worn on edge both (5.2.3 (e))	





MOT #5		2021-12-23 12:20
MOT test i	number	988838465029
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords	s (5.2.3 (d) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4		2021-01-05 14:10
MOT test	number	592761059864
Result		✓ Passed
Advice	Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2020-01-03 14:41
MOT test number	568665505466
Result	✓ Passed
MOT #2	2019-01-02 16:40
MOT test number	680056733905
Result	✓ Passed
MOT #1	2018-01-04 12:52
MOT test number	761597745256
Result	✓ Passed



Tax & MOT check

Tax due: 1 January 2025	✓ Taxed	Expires: 13 January 2025	✓ MOT
Tax status			Valid until 1 January
Days left			246
MOT expiry date			13 January 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	A PLANE
Туре	
Damage 2	AMPLE
	A A A A A A A A A A A A A A A A A A A
Date	1. E
Category	ant
Туре	

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	
formed methods	
Carrent registration	
Pate since	
Farle since Carrent registration	
Faite since Faite since Faite since	1111-21-22





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-23
Last registration	2023-12-21
Complete history	<u>See info</u>



Registration #1	2014-09-23	17 mi
Registration #2	2018-01-04	37.996 mi
Registration #3	2019-01-02	42.517 mi
Registration #4	2020-01-03	45.691 mi
Registration #5	2021-01-05	47.860 mi
Registration #6		11.777 esi
Registration #7	2021-12-23	53.138 mi
Registration #8		11.117 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 esi





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1777 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1525 kg
Max. allowed weight	2005 kg
Additional information	
Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	65193032120397