



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	HORIZON HDI TEPEE S
Colour	Brown
Year of manufacture	2014
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-03-28
MOT pass rate	50 %
MOT passed	5
Failed MOT tests	5
Total advice items	14
Total items failed	11

MOT #10	2023-03-28 16:56
MOT test number	304740803326
Result	✓ Passed
Next expiry date	2024-03-28
Advice	Offside rear tyre tread on 3mm...

MOT #9	2023-03-28 11:17
MOT test number	120005154309
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Offside rear tyre tread on 3mm...

MOT #8	2022-03-29 12:32
MOT test number	659871450108
Result	✓ Passed

**MOT #7** 2022-03-25 07:32**MOT test number** 429295979174**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2018-10-16 15:46**MOT test number** 106741756737**Result** ✓ Passed**MOT #5** 2018-10-16 10:24**MOT test number** 363281911028**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #4** 2017-12-19 11:48**MOT test number** 703523499282**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front discs worn advise**MOT #3** 2017-12-19 11:48**MOT test number** 800386249608**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front discs worn advise**MOT #2** 2017-03-03 11:37**MOT test number** 294951859273**Result** ✓ Passed**MOT #1** 2017-02-21 11:10**MOT test number** 490538454147**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-05-14
Last registration	2023-03-28
Complete history	See info



Registration #1	2014-05-14	17 mi
Registration #2	2017-02-21	29.821 mi
Registration #3	2017-03-03	30.253 mi
Registration #4	2017-12-19	45.376 mi
Registration #5	2017-12-19	45.376 mi
Registration #6	2018-10-16	58.998 mi
Registration #7	2019-05-29	75.277 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1601 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JBEM0319986