




report date: 2024-03-29

General information

Make	MINI
Model	FIRST ONE
Colour	Blue
Year of manufacture	2013
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-05-10
Pictures	28
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-28
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	3

MOT #10	2024-04-22 14:42
MOT test number	719415267495
Result	✓ Passed
Next expiry date	2025-04-28

MOT #9	2023-04-03 15:38
MOT test number	734603880027
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge N/S FRONT TYRE WORN OUTER EDGE, LOW TREAD DEPTH 2.0MM (5.2.3 (e))
Advice	Rear Tyre slightly damaged/cracking or perishing O/S & N/S REAR TYRES PERISHED/CRACKING ON EDGES (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge O/S FRONT TYRE WORN ON EDGES, LOW TREAD DEPTH 2.0MM (5.2.3 (e))

MOT #8	2022-04-29 13:53
MOT test number	267571845469
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7	2021-10-22 11:30
MOT test number	488165500148
Result	✓ Passed



MOT #6 2020-10-09 10:59

MOT test number 451038610097

Result ✓ Passed

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #5 2019-10-31 08:48

MOT test number 612001758910

Result ✓ Passed

Minor Brake fluid warning lamp illuminated (1.1.10 (f))

Advice Under side of vehicle not fully inspected due to full covers fitted

MOT #4 2018-07-24 08:50

MOT test number 478011023525

Result ✓ Passed

MOT #3 2018-07-21 10:52

MOT test number 317415356391

Result ✗ Failed

Fail Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))

Fail Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

Fail Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #2 2017-07-15 14:21

MOT test number 161405918599

Result ✓ Passed

Advice Oil leak

Advice Nearside Front tyre worn outer edge



MOT #1 2016-07-16 12:48

MOT test number 368581707094

Result ✓ Passed

Advice Nearside Front Oil leak driveshaft seal



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
28 April 2025

Tax status Valid until 1 May

Days left 1

MOT expiry date 28 April 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	WD13CDE
Plate since	2019-03-29
Current registration	WD13CDE
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-07-26
Last registration	2024-04-22
Complete history	See info



Registration #1	2013-07-26	29 mi
Registration #2	2016-07-16	18.699 mi
Registration #3	2017-07-15	24.161 mi
Registration #4	2018-07-21	45.497 mi
Registration #5	2018-07-24	45.499 mi
Registration #6	2019-10-31	65.487 mi
Registration #7	<i>[blurred]</i>	<i>[blurred]</i>
Registration #8	<i>[blurred]</i>	<i>[blurred]</i>
Registration #9	<i>[blurred]</i>	<i>[blurred]</i>
Registration #10	<i>[blurred]</i>	<i>[blurred]</i>
Registration #11	<i>[blurred]</i>	<i>[blurred]</i>
Registration #12	<i>[blurred]</i>	<i>[blurred]</i>

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles

2

Engine number

A474J474