



RENAULT

HN6IDF J

report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	White
Year of manufacture	2011
Top speed	91 mph
0 - 60 mph	19.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	185 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	54.3 mpg





Internet history

Entry 1

Date	2021-11-04
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-05-03
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	27
Total items failed	15

MOT #14	2023-05-04 11:52
MOT test number	549819776305
Result	✓ Passed
Next expiry date	2024-05-03
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-05-02 10:28
MOT test number	335393315025
Result	✗ Failed
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cracked badly to cords (5.2.3 (d) (i))
Fail	Fuel cap/sealing device ineffective (6.1.3 (b) (i))
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Windscreen damaged and affecting the driver's view of the road badly cracked (3.2 (a) (ii))

MOT #12	2022-04-30 07:54
MOT test number	663356781618
Result	✓ Passed

**MOT #11** 2022-04-30 07:54**MOT test number** 232605792062**Result** ✗ Failed

**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #10** 2021-05-01 14:17**MOT test number** 801633314951**Result** ✓ Passed**MOT #9** 2020-04-25 07:59**MOT test number** 461372433584**Result** ✓ Passed

**Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #8** 2019-05-15 15:25**MOT test number** 803443781479**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Power steering component has slight seepage from a component Rack (2.1.5 (a))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Advice** Brake pipe corroded, covered in grease or other material Both rear (1.1.11 (c))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear at rear (1.1.11 (c))

**MOT #7** 2019-05-15 12:58**MOT test number** 369011001942**Result** ✗ Failed

- Advice** Brake pipe corroded, covered in grease or other material Both rear (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear at rear (1.1.11 (c))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Power steering component has slight seepage from a component Rack (2.1.5 (a))
- Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2018-05-30 13:43**MOT test number** 291307967947**Result** ✓ Passed**MOT #5** 2017-04-05 13:06**MOT test number** 394965114365**Result** ✓ Passed**MOT #4** 2017-04-05 09:50**MOT test number** 345286045951**Result** ✗ Failed

- Fail** Nearside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Offside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #3**

2016-03-31 16:53

**MOT test number**

405039761809

**Result**

✓ Passed

**Advice** ...Thanx 4visiting us...**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt ( leaking @ small end ) (2.5.C.1a)**MOT #2**

2016-03-31 10:01

**MOT test number**

748844927700

**Result**

✗ Failed

**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt ( leaking @ small end ) (2.5.C.1a)**Advice** NOTE:: Spare tyre deflated**Fail** Offside Headlamp aim too low (Adjusted) (1.8)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Both front tyres have worn low & just within the legal limit**Fail** Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c)**Advice** O/s rear tyre torn (see inner-band tread area & both rear tyre valves are perishing)**Advice** ...Thanx 4visiting us...**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Continued: (n/s unevenly worn & both valves are perishing)**MOT #1**

2015-03-11 15:16

**MOT test number**

526900575072

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)



Tax & MOT check

✕  
Untaxed

Tax expired:  
12 April 2024

✓  
MOT

Expires:  
3 May 2024

Tax status	Expired at 12 April 2024
Days left	17 days too late
MOT expiry date	3 May 2024
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>HN61DFJ</b>
Plate since	2019-09-28
Current registration	<b>HN61DFJ</b>
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-02
Last registration	2023-05-04
Complete history	<a href="#">See info</a>



Registration #1	2011-11-02	8 mi
Registration #2	2015-03-11	56.896 mi
Registration #3	2016-03-31	77.184 mi
Registration #4	2016-03-31	77.184 mi
Registration #5	2017-04-05	98.841 mi
Registration #6	2017-04-05	98.841 mi
Registration #7	2018-05-30	27.792 mi
Registration #8	2019-05-15	38.023 mi
Registration #9	2020-05-01	55.277 mi
Registration #10	2020-05-01	55.277 mi
Registration #11	2020-05-01	55.277 mi
Registration #12	2020-05-01	55.277 mi
Registration #13	2020-05-01	55.277 mi
Registration #14	2020-05-01	55.277 mi
Registration #15	2020-05-01	55.277 mi
Registration #16	2023-05-04	55.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D096644