



PEUGEOT



FL55CMX


report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Red
Year of manufacture	2005
Top speed	106 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-10
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-11
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	67
Total items failed	3

MOT #20	2024-04-09 14:14
---------	------------------

MOT test number	306498050698
-----------------	--------------

Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #19**

2022-10-12 14:04

MOT test number

783424862512

Result

✓ Passed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #18

2022-10-12 11:46

MOT test number

208207607611

Result

✗ Failed

- MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #17

2021-08-14 09:26

MOT test number

774750121200

Result

✓ Passed

- Advice** Front Play in steering rack inner joint(s) n.s & o.s
- Advice** Oil leak, but not excessive slight on transmission (8.4.1 (a) (i))
- Advice** Parking brake lever brake has little reserve travel

**MOT #16**

2021-08-14 09:26

MOT test number

669154276699

Result**✗ Failed****Advice** Oil leak, but not excessive slight on transmission (8.4.1 (a) (i))**Advice** Parking brake lever brake has little reserve travel**Advice** Front Play in steering rack inner joint(s) n.s & o.s**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #15**

2020-09-19 15:32

MOT test number

605663005164

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Handbrake travel , need adjustment**MOT #14**

2020-09-19 09:48

MOT test number

342005161000

Result**✗ Failed****MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt torn (5.3.4 (b) (ii))**MAJOR** Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both sides (5.3.4 (b) (ii))**MAJOR** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt torn (2.1.3 (g) (ii))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Handbrake travel , need adjustment**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2019-09-21 10:06**MOT test number** 519307851522**Result** ✓ Passed**MOT #12** 2018-09-21 09:49**MOT test number** 994228452357**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #11** 2017-09-21 09:05**MOT test number** 489544957137**Result** ✓ Passed**Advice** Nearside Rear position lamp(s) deteriorated, but still visible from a reasonable distance water ingress (1.1.A.3d)**Advice** Play in steering rack inner joint(s) both**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #10** 2016-09-17 12:43**MOT test number** 296149382682**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement middle wish bone bush (2.4.G.2)**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement middle wish bone bush (2.4.G.2)**Advice** Oil leak under engine oil sump nut**Advice** Nearside Rear stop light lens has water condensation



MOT #9 2015-09-20 13:53

MOT test number 911771884394

Result ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear tyre is worn low on the inner edge
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Front windscreen wipers slightly smear the screen
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #8 2014-09-20 14:27

MOT test number 355723764408

Result ✓ Passed

- Notice** Nearside front tyre is wearing on the outer edge
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Nearside rear tyre is deteriorated
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #7** 2014-09-20 10:02**MOT test number** 907823564235**Result** ✗ Failed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Nearside rear tyre is deteriorated**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Offside rear tyre is deteriorated and has a puncture**Notice** Nearside front tyre is wearing on the outer edge**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2013-09-20 13:19**MOT test number** 818393463269**Result** ✓ Passed**MOT #5** 2012-09-20 11:51**MOT test number** 827614662259**Result** ✓ Passed**MOT #4** 2011-09-20 10:52**MOT test number** 658503961238**Result** ✓ Passed**Notice** Air bag light on



MOT #3	2010-09-20 12:56
MOT test number	942853860209
Result	✓ Passed
MOT #2	2009-09-24 12:24
MOT test number	250317669258
Result	✓ Passed
MOT #1	2008-09-24 10:54
MOT test number	221008768279
Result	✓ Passed
<div><div>Notice</div>Front tyres wearing slightly unevenly</div> <div><div>Notice</div>Nail in offside front tyre</div>	



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

X

MOT

Expired:
11 October 2023

Tax status	Expired at 1 March 2024
Days left	60 days too late
MOT expiry date	11 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-30
Last registration	2024-04-09
Complete history	See info



Registration #1	2005-09-30	16 mi
Registration #2	2008-09-24	8.108 mi
Registration #3	2009-09-24	10.593 mi
Registration #4	2010-09-20	15.098 mi
Registration #5	2011-09-20	19.230 mi
Registration #6	2012-09-20	22.566 mi
Registration #7	2013-09-20	26.656 mi
Registration #8	2014-09-20	30.697 mi
Registration #9	2014-09-20	30.697 mi
Registration #10	2015-09-20	36.407 mi
Registration #11	2016-09-17	41.349 mi
Registration #12	2016-09-17	41.349 mi
Registration #13	2016-09-17	41.349 mi
Registration #14	2016-09-17	41.349 mi
Registration #15	2016-09-17	41.349 mi
Registration #16	2016-09-17	41.349 mi
Registration #17	2016-09-17	41.349 mi
Registration #18	2016-09-17	41.349 mi
Registration #19	2016-09-17	41.349 mi
Registration #20	2016-09-17	41.349 mi
Registration #21	2016-09-17	41.349 mi
Registration #22	2016-09-17	41.349 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FSR95191649