



TOYOTA



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | TOYOTA |
| Model | VERSO D-4D TR |
| Colour | Blue |
| Year of manufacture | 2011 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 125 BHP |
| Max. torque | 310 Nm at 1.800 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2021-07-14 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-14 |
| Pictures | 44 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-20 |
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 19 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #13 | 2024-01-18 10:44 |
| MOT test number | 324926373720 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-20 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge worn very close to legal limit (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #12 | 2023-01-19 15:22 |
| MOT test number | 650243161763 |
| Result | ✓ Passed |
| Advice | Offside Rear Seat belt slightly damaged back seat belt has small cut in webbing but not deemed excessively damaged (7.1.2 (b) (i)) |
| Minor | Nearside Front Windscreen damaged but not adversely affecting driver's view stone chip lower corner (3.2 (a) (i)) |

| | |
|-----------------|--|
| MOT #11 | 2023-01-19 12:53 |
| MOT test number | 998202036430 |
| Result | ✗ Failed |
| MAJOR | Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) |
| Advice | Offside Rear Seat belt slightly damaged back seat belt has small cut in webbing but not deemed excessively damaged (7.1.2 (b) (i)) |
| Minor | Nearside Front Windscreen damaged but not adversely affecting driver's view stone chip lower corner (3.2 (a) (i)) |

**MOT #10** 2022-01-13 13:58**MOT test number** 700945614073**Result** ✓ Passed**Advice** Knock in steering column**Advice** Offside Rear Seat belt slightly damaged very small cut in belt (7.1.2 (b) (i))**MOT #9** 2021-01-05 15:57**MOT test number** 281532320187**Result** ✓ Passed**MOT #8** 2020-01-16 11:49**MOT test number** 929715983850**Result** ✓ Passed**MOT #7** 2019-01-21 13:51**MOT test number** 132124013306**Result** ✓ Passed**Advice** Both rear tyres 2mm on outer shoulders**Advice** Damage/chips in windscreen(rest of swept area)**MOT #6** 2018-02-08 17:18**MOT test number** 119301914445**Result** ✓ Passed**MOT #5** 2017-02-15 16:36**MOT test number** 930772021225**Result** ✓ Passed

**MOT #4** 2017-02-15 12:52**MOT test number** 223284295348**Result** ✗ Failed**Advice** Advise large lip on front discs**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #3** 2016-02-12 17:03**MOT test number** 888643800131**Result** ✓ Passed**Advice** Front brake discs worn**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Emissions to clean to read due to derv/part/filter/fitted**Advice** Front brake pads worn**MOT #2** 2015-02-02 14:56**MOT test number** 129943835000**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-02-28 08:42**MOT test number** 255719554009**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 93 |
| MOT expiry date | 20 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2011-03-01 |
| Last registration | 2024-01-18 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-03-01 | 12 mi |
| Registration #2 | 2014-02-28 | 26.962 mi |
| Registration #3 | 2015-02-02 | 35.563 mi |
| Registration #4 | 2016-02-12 | 45.515 mi |
| Registration #5 | 2017-02-15 | 53.833 mi |
| Registration #6 | 2017-02-15 | 53.833 mi |
| Registration #7 | 2018-02-08 | 62.835 mi |
| Registration #8 | 2019-01-21 | 70.866 mi |
| Registration #9 | 2020-01-21 | 70.866 mi |
| Registration #10 | 2020-01-21 | 70.866 mi |
| Registration #11 | 2020-01-21 | 70.866 mi |
| Registration #12 | 2020-01-21 | 70.866 mi |
| Registration #13 | 2020-01-21 | 70.866 mi |
| Registration #14 | 2020-01-21 | 70.866 mi |
| Registration #15 | 2020-01-21 | 70.866 mi |
| Registration #16 | 2020-01-21 | 70.866 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 75% |
| Pedestrian | 69% |
| Safety systems | 86% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1790 mm |
| Height | 1620 mm |
| Length | 4440 mm |
| Wheel base | 2780 mm |
| Kerb weight | 1625 kg |
| Max. allowed weight | 2260 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|------------------------|------------|
| Number of axles | 2 |
| Engine number | 1AD5602172 |