





report date: 2024-03-28

General information

Make	CITROEN
Model	C4 PICASSO BLUEHDI EDITION PICASSO
Colour	Blue
Year of manufacture	2016
Top speed	111 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	101 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 4

Date 2022-02-07

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Date 2021-12-05	
-----------------	--

Pictures 25

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date	2021-12-02
Pictures	1

Listing price <u>View report</u>



source: autotrader.co.uk

Entry 1

Date	2021-12-01

CarCheck.co.uk page 2/11

Pictures 27

Listing price

View report









source: cargurus.co.uk



report date: 2024-03-28

MOT history

MOT expiry date	2025-02-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	6
Total items failed	4

MOT #10	2024-01-19 09:17
MOT test number	727792882417
Result	✓ Passed
Next expiry date	2025-02-02

MOT #9	2023-01-28 10:55
MOT test number	397450205250
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8		2023-01-28 10:55
MOT test number		164570675366
Result		X Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	
Advice Rear Brake pad(s	s) wearing thin (1.1.13 (a) (ii))	
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	

MOT #7	2022-02-03 16:14
MOT test number	870377910572
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #6 2021-06-03 14:01

MOT test number 966186132488

Result
✓ Passed

MOT #5 2020-07-21 08:40

MOT test number 516399226014

Result

Passed

MOT #4 2020-07-20 14:33

MOT test number 806013447148

Result X Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing heavily perished plus outer sidewall damage (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing heavily perished (5.2.3 (d) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords plus perished (5.2.3 (d) (i))

MOT #3 2019-03-25 13:00

MOT test number 526750970902

Result
✓ Passed

MOT #2 2018-11-28 09:42

MOT test number 190241779033

Result
✓ Passed

Minor Nearside Rear reflector insecure (4.8.1 (b) (i))

MOT #1 2018-11-28 09:42

MOT test number 122464702220

Result X Failed

Pass with rectification Windscreen washer provides insufficient washer liquid Added enough water to

Minor Nearside Rear reflector insecure (4.8.1 (b) (i))

pass test (3.5 (a))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2016-02-08
Last registration	2024-01-19
Complete history	See info



Registration #1	2016-02-08	27 mi
Registration #2	2018-11-28	3.738 mi
Registration #3	2018-11-28	3.738 mi
Registration #4	2019-03-25	3.983 mi
Registration #5	2020-07-20	10.897 mi
Registration #6	2020-07-21	10.898 mi
Registration #7	2021-06-03	14.780 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHA3137763

CarCheck.co.uk page 11/11