



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	White
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 2


Date	2023-12-11
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-07-27
Pictures	20
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2023-03-18
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	26
Total items failed	16

MOT #122023-03-17 08:05

MOT test number933221834520

ResultX Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #11**

2022-03-19 11:16

**MOT test number**

766795559751

**Result**

✓ Passed

**Minor** Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement LOWER ARM REAR BUSH (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement LOWER ARM REAR BUSH (5.3.4 (a) (i))**MOT #10**

2021-03-13 12:45

**MOT test number**

126039540008

**Result**

✓ Passed

**MOT #9**

2021-03-09 08:52

**MOT test number**

649464603565

**Result**

✗ Failed

**Fail** Offside Rear Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**Fail** Nearside Rear Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Emissions not tested (8.2.2.2 (e))**Fail** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))

**MOT #8** 2020-03-17 12:30**MOT test number** 843942464277**Result** ✓ Passed**MOT #7** 2019-01-30 13:48**MOT test number** 829489166162**Result** ✓ Passed

- Advice** Oil leak, but not excessive From engine (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #6** 2019-01-29 15:34**MOT test number** 778910782197**Result** ✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive From engine (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Rear Reversing lamp inoperative (4.6.1 (a))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #5** 2018-01-24 09:43**MOT test number** 486482516974**Result** ✓ Passed

- Advice** Nearside Front tyre worn on shoulders
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Centre to rear exhaust flange deteriorated
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #4** 2017-01-30 16:14**MOT test number** 673562102295**Result** ✓ Passed**MOT #3** 2016-03-10 11:19**MOT test number** 525409706057**Result** ✓ Passed**MOT #2** 2015-03-12 14:59**MOT test number** 417711675025**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2015-03-11 11:58**MOT test number** 308240575019**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:  
1 August 2023

X

MOT

Expired:  
18 March 2023

Tax status	Expired at 1 August 2023
Days left	273 days too late
MOT expiry date	18 March 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>SO12VVN</b>
Plate since	2019-06-29
Current registration	 <b>SO12VVN</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-05-07
Last registration	2023-03-17
Complete history	<a href="#">See info</a>



Registration #1	2012-05-07	14 mi
Registration #2	2015-03-11	25.125 mi
Registration #3	2015-03-12	25.125 mi
Registration #4	2016-03-10	35.357 mi
Registration #5	2017-01-30	39.315 mi
Registration #6	2018-01-24	59.060 mi
Registration #7	2019-01-29	82.856 mi
Registration #8	2020-05-20	95.277 mi
Registration #9	2020-05-20	95.277 mi
Registration #10	2020-05-20	95.277 mi
Registration #11	2020-05-20	95.277 mi
Registration #12	2020-05-20	95.277 mi
Registration #13	2020-05-20	95.277 mi
Registration #14	2020-05-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	145854K