



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Red
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg




LABEL UNKNOWN



Internet history

Entry 2

Date	2021-09-08
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-29
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #17	2021-06-22 11:21
MOT test number	833796957575
Result	✓ Passed
Next expiry date	2022-06-21
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16	2021-06-11 12:14
MOT test number	325354877262
Result	✗ Failed
MAJOR	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
DANGEROUS	Stop lamp(s) all not working (4.3.1 (a) (iii))
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Oil leaking excessively from engine (8.4.1 (a) (i))

MOT #15	2020-03-19 13:19
MOT test number	473677957470
Result	✓ Passed

MOT #14	2019-04-03 09:01
MOT test number	434718181515
Result	✓ Passed
Advice	Slight oil leak
Advice	Offside Rear Tyre perished and worn on edge
Advice	Front engine stabilizer bush worn



MOT #13	2018-04-04 07:20
----------------	------------------

MOT test number	488999073735
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2017-04-12 15:39
----------------	------------------

MOT test number	665197916332
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2017-04-12 15:39
----------------	------------------

MOT test number	519748564065
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Stop lamp not working All (1.2.1b)
--------------------------------	------------------------------------

Pass with rectification	Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc clip broken (2.5.C.1a)
--------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------

MOT #10	2016-03-11 16:33
----------------	------------------

MOT test number	539975293424
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2015-03-20 12:39
---------------	------------------

MOT test number	376839075079
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2014-03-26 17:22
---------------	------------------

MOT test number	108345384400
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2013-04-27 11:23
---------------	------------------

MOT test number	207657013454
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #6	2013-04-27 11:23
MOT test number	636157313168
Result	✗ Failed
Pass with rectification Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)	
MOT #5	2012-04-26 13:31
MOT test number	389877212133
Result	✓ Passed
MOT #4	2011-04-28 15:21
MOT test number	289988811196
Result	✓ Passed
MOT #3	2010-04-29 16:36
MOT test number	854999910123
Result	✓ Passed
MOT #2	2009-07-09 09:25
MOT test number	984180499190
Result	✓ Passed
MOT #1	2009-07-08 09:13
MOT test number	394769689155
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29
Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 PO56WGU
Plate since	2019-06-29
Current registration	 PO56WGU
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-04
Last registration	2021-06-22
Complete history	See info



Registration #1	2006-09-04	14 mi
Registration #2	2009-07-08	10.625 mi
Registration #3	2009-07-09	10.625 mi
Registration #4	2010-04-29	21.934 mi
Registration #5	2011-04-28	27.276 mi
Registration #6	2012-04-26	32.994 mi
Registration #7	2013-04-27	38.964 mi
Registration #8	2014-03-26	45.496 mi
Registration #9	2015-03-20	54.252 mi
Registration #10	2016-03-11	61.662 mi
Registration #11	2016-03-11	61.662 mi
Registration #12	2016-03-11	61.662 mi
Registration #13	2016-03-11	61.662 mi
Registration #14	2016-03-11	61.662 mi
Registration #15	2016-03-11	61.662 mi
Registration #16	2016-03-11	61.662 mi
Registration #17	2016-03-11	61.662 mi
Registration #18	2016-03-11	61.662 mi
Registration #19	2016-03-11	61.662 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	19GK2653