





report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Silver
Year of manufacture	2008
Top speed	132 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2022-07-19

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-05-16
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	20
Total items failed	3

MOT #17	2024-04-25 14:04
MOT test number	958328280223
Result	✓ Passed
Next expiry date	2025-05-16

MOT #16	2023-05-05 11:18
MOT test number	290878009478
Result	✓ Passed

MOT #15		2022-05-05 07:59
MOT test n	number	745772732714
Result		✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside hand brake binding slightly	

MOT #14	2021-05-17 15:01
MOT test number	360879339749
Result	√ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2020-07-11 08:24 592949026606 **MOT** test number ✓ Passed Result **Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f)) Advice Offside Rear Brake pad(s) wearing thin approx. 2mm (1.1.13 (a) (ii)) Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bushes (5.3.4 (a) (i))

 MOT #12
 2019-05-29 14:50

 MOT test number
 826284101235

 Result
 ✓ Passed

MOT test number

Result

Nearside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9 2017-05-25 13:13 **MOT test number** 300202386484 Result ✓ Passed MOT #8 2016-05-23 14:07 **MOT test number** 855637550943 Result ✓ Passed MOT #7 2016-05-23 11:13 **MOT test number** 816049503639 Result × Failed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6	2015-05-28 16:08
MOT test number	619458145148
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2014-05-30 14:03
MOT test number	565350054197
Result	✓ Passed
MOT #4	2014-05-30 12:44
MOT test number	199010554152
Result	X Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOI #3	2013-05-31 17:11
MOT test number	129921653170
Result	✓ Passed

MOT #2	2012-11-07 10:47
MOT test number	907842812328

Result \rightarrow Passed

MOT #1 2011-11-09 11:40

MOT test number 456803411356

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Both rear tyre worn inside

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside rear brake grabbing slightly (3.7.A.5b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	16 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

*		
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		Α

	More info	>
Plate changes See in this check if this HONDA had different number plates.		
Number of plates		,
Correct registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-12
Last registration	2024-04-25
Complete history	See info



Registration #1	2008-11-12	7 mi
Registration #2	2011-11-09	25.441 mi
Registration #3	2012-11-07	33.971 mi
Registration #4	2013-05-31	38.909 mi
Registration #5	2014-05-30	50.529 mi
Registration #6	2014-05-30	50.529 mi
Registration #7	2015-05-28	59.736 mi
Registration #8	2016-05-23	64.871 mi
Registration #9	2016-05-23	64.871 mi
Registration #10	2017-05-25	70.481 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	N22B11001920

CarCheck.co.uk page 13/13