



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Grey
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 2



Date	2021-10-12
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-27
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-09-03
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	67
Total items failed	10

MOT #19	2022-09-01 07:31
---------	------------------

MOT test number	767632689721
-----------------	--------------

Result	✓ Passed
Next expiry date	2023-09-03
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Corrosion forming on underside of vehicle
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Radiator support corroded

**MOT #18**

2022-08-31 09:09

**MOT test number**

452932521775

**Result****✗ Failed**

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Corrosion forming on underside of vehicle
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Radiator support corroded
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17**

2021-08-11 11:28

**MOT test number**

558722327786

**Result**

✓ Passed

- Advice** Front brake discs (inner face) becoming lipped/scored
- Advice** Exhaust has a minor leak of gases (rear section) ( exhaust system sitting close to plastic fuel tank - requires adjustment)
- Advice** Nearside rear brake flex hose slightly twisted
- Advice** Offside front tyre scrubbing off slightly (inner edge)
- Advice** Nearside front antiroll bar link (lower ball joint) dust cover deteriorated
- Advice** General corrosion on underside of vehicle - rear axle, body, suspension, brake component's
- Advice** Slight oil leak
- Advice** Front lower radiator cross member corroded

**MOT #16**

2020-08-10 14:57

**MOT test number**

886130738264

**Result**

✓ Passed

- Advice** Slight oil leak
- Advice** Offside front trackrod end has slight play
- Advice** Nearside front undertray loose
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** General corrosion on underside of vehicle

**MOT #15**

2019-08-19 12:42

**MOT test number**

794800041032

**Result**

✓ Passed

- Advice** Exhaust manifold heatshield loose
- Advice** Nearside front undertray/shield loose
- Advice** Offside rear brake pads worn
- Advice** Front brake discs worn. lipped/scored/corroded. recommend replacment
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14**

2019-08-17 09:28

**MOT test number**

588234266462

**Result**

✗ Failed

- Advice** Offside rear brake pads worn
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside front undertray/shield loose
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Exhaust manifold heatshield loose
- Advice** Front brake discs worn. lipped/scored/corroded. recommend replacment

**MOT #13**

2018-09-03 15:13

**MOT test number**

513295491405

**Result**

✓ Passed

- Advice** Exhaust manifold heat shield loose
- Advice** Nearside front undertray/shield loose
- Advice** Nearside rear child seat fitted, obscuring full seat/seatbelt inspection
- Advice** Slight oil leak
- Advice** Front brake discs becoming worn. lipped/scored

**MOT #12**

2018-09-03 09:41

**MOT test number**

550364719765

**Result**

✗ Failed

- Advice** Exhaust manifold heat shield loose
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside front undertray/shield loose
- Advice** Nearside rear child seat fitted, obscuring full seat/seatbelt inspection
- Advice** Slight oil leak
- Advice** Front brake discs becoming worn. lipped/scored

**MOT #11**

2017-08-17 14:22

**MOT test number**

402933366127

**Result**

✓ Passed

- Advice** Exhaust heatshield insecure
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #10** 2017-08-17 08:21**MOT test number** 577704155285**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust heatshield insecure**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2016-08-24 11:59**MOT test number** 189145840255**Result** ✓ Passed**MOT #8** 2016-08-24 08:37**MOT test number** 315435138876**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7** 2015-08-06 10:56**MOT test number** 746815378924**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2014-08-30 09:22**MOT test number** 466702644221**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)



**MOT #5** 2013-08-17 09:57**MOT test number** 737169323287**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #4** 2012-09-03 09:18**MOT test number** 648727942263**Result** ✓ Passed**Notice** Exhaust back box deteriorated but not leaking.**MOT #3** 2011-08-22 13:42**MOT test number** 456914231210**Result** ✓ Passed**Notice** Exhaust back box slightly deteriorated**MOT #2** 2010-09-04 10:10**MOT test number** 542727140233**Result** ✓ Passed**MOT #1** 2010-09-02 09:26**MOT test number** 540185840292**Result** ✗ Failed**Notice** Front brake discs worn**Fail** Nearside Side repeater insecure (1.4.A.2b)**Notice** Front tyres worn on inner edges



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-07-27
Last registration	2022-09-01
Complete history	<a href="#">See info</a>



Registration #1	2007-07-27	14 mi
Registration #2	2010-09-02	17.916 mi
Registration #3	2010-09-04	17.916 mi
Registration #4	2011-08-22	28.387 mi
Registration #5	2012-09-03	42.848 mi
Registration #6	2013-08-17	53.438 mi
Registration #7	2014-08-30	61.120 mi
Registration #8	2015-08-06	71.319 mi
Registration #9	2016-08-24	83.917 mi
Registration #10	2016-08-24	83.917 mi
Registration #11	2017-08-17	98.796 mi
Registration #12	2018-08-01	113.675 mi
Registration #13	2019-07-25	128.554 mi
Registration #14	2020-07-19	143.433 mi
Registration #15	2021-07-13	158.312 mi
Registration #16	2022-06-27	173.191 mi
Registration #17	2023-06-21	188.070 mi
Registration #18	2024-06-15	202.949 mi
Registration #19	2025-06-09	217.828 mi
Registration #20	2026-05-23	232.707 mi
Registration #21	2027-05-17	247.586 mi
Registration #22	2028-05-11	262.465 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1188390