



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Silver
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J






Internet history

Entry 2

Date	2021-07-28
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-27
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-18
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #16	2023-09-19 11:33
MOT test number	697765586777
Result	✓ Passed
Next expiry date	2024-09-18

MOT #15	2022-08-22 06:31
MOT test number	255963306355
Result	✓ Passed
Advice	Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2022-08-22 06:31
MOT test number	579051915051
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Nearside Rear Outer Suspension arm insecurely attached (5.3.3 (a) (i))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13** 2021-07-19 10:38**MOT test number** 678733239943**Result** ✓ Passed**MOT #12** 2020-07-30 09:54**MOT test number** 457138722571**Result** ✓ Passed**MOT #11** 2019-07-27 09:55**MOT test number** 926882082324**Result** ✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))

MOT #10 2018-07-23 10:20**MOT test number** 415464899714**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2017-07-24 15:51**MOT test number** 366777333818**Result** ✓ Passed**MOT #8** 2017-07-24 14:42**MOT test number** 480906645062**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-09-05 14:42**MOT test number** 514647436550**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-09-04 08:38**MOT test number** 437429315356**Result** ✓ Passed**MOT #5** 2014-09-08 09:01**MOT test number** 167591954214**Result** ✓ Passed**Notice** Both front tyres wearing on inner tread also cracking badly on outer sidewalls**MOT #4** 2013-09-02 17:32**MOT test number** 759335443234**Result** ✓ Passed**Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-09-04 13:39**MOT test number** 987448742241**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-09-09 14:22**MOT test number** 817972351232**Result** ✓ Passed



MOT #1	2011-06-02 13:35
MOT test number	539393751135
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 December 2022

✓

MOT

Expires:
18 September 2024

Tax status	Expired at 1 December 2022
Days left	515 days too late
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-28
Current registration	*****
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-05-21
Last registration	2023-09-19
Complete history	See info



Registration #1	2008-05-21	12 mi
Registration #2	2011-06-02	62.388 mi
Registration #3	2011-09-09	62.499 mi
Registration #4	2012-09-04	70.055 mi
Registration #5	2013-09-02	77.798 mi
Registration #6	2014-09-08	86.092 mi
Registration #7	2015-09-04	94.184 mi
Registration #8	2016-09-05	102.917 mi
Registration #9	2017-07-24	108.682 mi
Registration #10	2017-07-24	108.682 mi
Registration #11	2019-05-20	111.377 mi
Registration #12	2019-05-20	111.377 mi
Registration #13	2019-05-20	111.377 mi
Registration #14	2019-05-20	111.377 mi
Registration #15	2019-05-20	111.377 mi
Registration #16	2019-05-20	111.377 mi
Registration #17	2019-05-20	111.377 mi
Registration #18	2019-05-20	111.377 mi
Registration #19	2019-05-20	111.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	560100