





report date: 2024-03-28

### General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Red
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/14



# Internet history

### Entry 1

Date 2022-01-29

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



# **MOT** history

MOT expiry date	2025-01-30
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	41
Total items failed	3

MOT #16	2024-01-23 13:22
MOT test number	415818444153
Result	<b>✓</b> Passed
Next expiry date	2025-01-30

MOT #15	2024-01-22 13:06

**MOT test number** 356161952714

**Result** X Failed

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

MOT #14	2023-01-25 13:05
MOT test number	291700533293
Result	✓ Passed
Advice Centre and o/s rear seats removed at time of test.	

MOT #13	202	2-01-27 09:58
MOT test	number 8	33378840314
Result		✓ Passed
Advice	Front shockers corroded	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/14



MOT #12 2021-01-19 09:14
MOT test number 832275812727

Result \( \sqrt{Passed} \)

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Exhaust corroded

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11 2020-01-22 10:00

**MOT test number** 837391962794

Result Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Exhaust corroded

CarCheck.co.uk page 4/14



MOT #10

MOT test number

Fesult

Advice Exhaust corroded

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9

MOT test number

725933566998

Result

Advice Offside Front Tyre worn close to the legal limit also very worn on edges (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit also very worn on edges (4.1.E.1)

Advice Oil leak

**MOT** #8 2018-01-30 09:57 **MOT** test number 772143208628 Result × Failed Fail Tailgate cannot be secured in the closed position (6.4.1) **Advice** Offside Front Tyre worn close to the legal limit also very worn on edges (4.1.E.1) Fail Horn not working (1.6.2a) Advice Nearside Front Tyre worn close to the legal limit also very worn on edges (4.1.E.1) **Advice** Oil leak

CarCheck.co.uk page 5/14



MOT test number
987420118929

Result

Advice
Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice
Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)

Advice
Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)

Advice
Engine covers and under trays fitted

MOT #6		2016-01-28 10:10
MOT test	number	175672810412
Result		✓ Passed
Advice	Under trays and engine cover fitted	
Advice	Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)	
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)	

MOT #5		2015-01-28 09:03
MOT test	number	817058025084
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8	3.3.1d)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	

CarCheck.co.uk page 6/14



MOT test number
748151834014

Result

Notice Under-trays fitted obscuring some underside components

Notice Spare wheel carrier lose

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice Engine covers fitted obscuring some components in the engine bay

 MOT #3
 2013-01-14 17:05

 MOT test number
 119564813480

 Result
 ✓ Passed

 MOT #2
 2012-01-25 12:06

 MOT test number
 438055922006

 Result
 ✓ Passed

MOT #1 2011-01-07 13:52

**MOT test number** 775807901057

Result \rightarrow Passed

**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

CarCheck.co.uk page 7/14



# Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	30 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



_	
<b>~</b>	history
IMMAR	

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	
HARMAN CO. C.	
********	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	UK AIS
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-01-25
Last registration	2024-01-23
Complete history	See info



Registration #1	2008-01-25	18 mi
Registration #2	2011-01-07	26.568 mi
Registration #3	2012-01-25	37.158 mi
Registration #4	2013-01-14	49.039 mi
Registration #5	2014-01-31	56.410 mi
Registration #6	2015-01-28	60.615 mi
Registration #7	2016-01-28	65.311 mi
Registration #8	2017-01-30	68.815 mi
Registration #9	2018-01-30	71.249 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,700 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 13/14



# Safety ratings

NCAP rating	***	0

**Video** <u>see crash video</u>

# Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBAW3003489

CarCheck.co.uk page 14/14