



KR56SLV


report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Silver
Year of manufacture	2006
Top speed	119 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	191 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.8 mpg
CO2 emission	205 g/km
CO2 label	K





Internet history

Entry 2

Date	2023-08-19
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-24
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-07
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #17 2023-08-08 13:50

MOT test number 796398927202

Result ✓ Passed

Next expiry date 2024-08-07

Advice Front Tyre worn close to legal limit/worn on edge 185/65/16 both front tyres unevenly worn on edges (5.2.3 (e))

Advice Driver's view Items removed from driver's view prior to test hanging from interior mirror (3.1 (a) (ii))

MOT #16 2022-09-12 11:54

MOT test number 789531244234

Result ✓ Passed

Advice Front Inner Brake pad(s) wearing thin offside and nearside front inner brake pads wearing thin (1.1.13 (a) (ii))

Advice Offside Rear 185/65/15 appears to have been driven on while flat ,inner and outer sidewalls damaged weakening tyre

MOT #15 2022-09-12 09:39

MOT test number 398281363360

Result ✗ Failed

Advice Front Inner Brake pad(s) wearing thin offside and nearside front inner brake pads wearing thin (1.1.13 (a) (ii))

Advice Offside Rear 185/65/15 appears to have been driven on while flat ,inner and outer sidewalls damaged weakening tyre

Fail Offside Windscreen wiper does not clear the windscreen effectively aero (3.4 (b) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively aero (3.4 (b) (ii))

**MOT #14** 2021-09-23 18:09**MOT test number** 924090802468**Result** ✓ Passed**MOT #13** 2020-11-18 13:07**MOT test number** 779905386183**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**MOT #12** 2019-12-11 13:47**MOT test number** 380902248529**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Slight play inner tie rod**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11** 2018-12-05 14:08**MOT test number** 860606311522**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing outer side wall (5.2.3 (d) (ii))**MOT #10** 2017-11-22 15:46**MOT test number** 544358493447**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit and slightly cracking (4.1.E.1)

**MOT #9** 2017-11-22 10:40**MOT test number** 216698660512**Result** ✗ Failed**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit and slightly cracking (4.1.E.1)**MOT #8** 2016-12-08 10:00**MOT test number** 413625989874**Result** ✓ Passed**Advice** Rear tyres slightly cracking on tread**MOT #7** 2015-12-09 14:22**MOT test number** 375268071032**Result** ✓ Passed**MOT #6** 2014-12-01 14:43**MOT test number** 405035234428**Result** ✓ Passed**Notice** All four tyres are starting to crack**MOT #5** 2013-11-26 11:05**MOT test number** 266160933338**Result** ✓ Passed**Notice** Exhaust deteriorated**MOT #4** 2012-12-06 09:39**MOT test number** 425511842493**Result** ✓ Passed



MOT #3	2011-11-18 09:42
MOT test number	358872021398
Result	✓ Passed
MOT #2	2010-12-02 09:32
MOT test number	914206430311
Result	✓ Passed
MOT #1	2009-12-01 09:00
MOT test number	404645539415
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Parking brake lever has a high travel
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-12-16
Last registration	2023-08-08
Complete history	See info



Registration #1	2006-12-16	25 mi
Registration #2	2009-12-01	22.924 mi
Registration #3	2010-12-02	28.988 mi
Registration #4	2011-11-18	34.787 mi
Registration #5	2012-12-06	39.599 mi
Registration #6	2013-11-26	43.785 mi
Registration #7	2014-12-01	49.025 mi
Registration #8	2015-12-09	52.846 mi
Registration #9	2016-12-08	58.020 mi
Registration #10	2017-11-22	62.883 mi
Registration #11	2018-05-29	65.377 mi
Registration #12	2019-05-29	65.377 mi
Registration #13	2020-05-29	65.377 mi
Registration #14	2021-05-29	65.377 mi
Registration #15	2022-05-29	65.377 mi
Registration #16	2023-05-29	65.377 mi
Registration #17	2024-05-29	65.377 mi
Registration #18	2025-05-29	65.377 mi
Registration #19	2026-05-29	65.377 mi
Registration #20	2027-05-29	65.377 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1326 kg
Max. allowed weight	1832 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LH4G1525632