



TOYOTA

**GRO6RXW**


report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4
Colour	Silver
Year of manufacture	2006
Gearbox	-

Engine & fuel consumption

Engine capacity	1.998 cc
Fuel type	Petrol
CO2 emission	202 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-18
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-05
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	77
Total items failed	18

MOT #21 2023-08-01 16:45

MOT test number 113328986869

Result ✓ Passed

Next expiry date 2024-08-05

**Minor** Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt twisted (2.1.3 (g) (i))

**Advice** Front and rear sub frame and suspension corroded

**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Front transfer box sight leak

**Advice** Offside and nearside front suspension arm rear bushes split soon

**Advice** Rear Exhaust has a minor leak of exhaust gases near mount point slight blow (6.1.2 (a))

MOT #20 2022-08-06 10:51

MOT test number 123877919083

Result ✓ Passed

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #19** 2022-08-06 10:51**MOT test number** 943661645523**Result** ✗ Failed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #18** 2021-11-02 12:22**MOT test number** 315964520559**Result** ✓ Passed**MOT #17** 2020-09-15 13:32**MOT test number** 792025450682**Result** ✓ Passed**MOT #16** 2019-09-27 13:37**MOT test number** 695556465131**Result** ✓ Passed**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Suspension arm corroded but not seriously weakened BOTH FRONT SUSPENSION ARMS N/S O/S (5.3.3 (b) (i))

**MOT #15**

2018-09-19 14:38

**MOT test number**

433653017169

**Result**

✓ Passed

**Advice**

Front Suspension arm corroded but not seriously weakened BOTH FRONT SUSPENSION ARM'S (5.3.3 (b) (i))

**Advice**

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice**

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2018-09-19 14:38

**MOT test number**

655756149075

**Result**

✗ Failed

**Pass with rectification**

Offside Front Position lamp not working (4.2.1 (a))

**Advice**

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice**

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice**

Front Suspension arm corroded but not seriously weakened BOTH FRONT SUSPENSION ARM'S (5.3.3 (b) (i))

**MOT #13**

2016-08-12 12:49

**MOT test number**

457468087779

**Result**

✓ Passed

**Advice**

Offside Rear coil spring corroded (2.4.C.1b)

**Advice**

Steering shaft noisy

**Advice**

Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #12**

2016-08-12 11:25

**MOT test number**

215368859906

**Result****✗ Failed****Advice** Steering shaft noisy**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #11**

2015-08-11 16:14

**MOT test number**

796823625233

**Result****✓ Passed****Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Steering shaft noisy

**MOT #10**

2015-08-11 11:27

**MOT test number**

349303025447

**Result****✗ Failed****Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Offside Rear Valve stem slightly damaged (4.1.D.1e)

**Fail**

Offside Registration plate lamp not working (1.1.C.1d)

**Fail**

Offside Rear Anti-roll bar linkage fractured (2.4.G.1)

**Advice**

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice**

Rear discs corroding

**Advice**

Nearside Rear Valve stem slightly damaged (4.1.D.1e)

**Fail**

Nearside Registration plate lamp not working (1.1.C.1d)

**Fail**

Nearside Rear Anti-roll bar linkage fractured (2.4.G.1)

**Advice**

Centre Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #9**

2014-08-15 16:46

**MOT test number**

646757324222

**Result****✓ Passed****Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Nearside Rear Anti-roll bar linkage slightly distorted (2.4.G.1)

**MOT #8** 2014-08-14 12:34**MOT test number** 216996824241**Result** ✗ Failed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Nearside Rear Anti-roll bar linkage slightly distorted (2.4.G.1)
- Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Heat shield insecure
- Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Offside Rear rear brake binding (3.7.B.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2013-08-16 13:15**MOT test number** 665518223211**Result** ✓ Passed

- Notice** Front discs in poor condition
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Front tyres wearing low
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)





MOT #6	2012-07-17 16:41
MOT test number	396639592176
Result	✓ Passed

MOT #5	2012-07-17 12:02
MOT test number	738739692185
Result	✗ Failed

- Notice** Heat shield insecure
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Nail in nearside rear tyre
- Notice** Rear discs in poor condition
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4	2011-07-26 14:07
MOT test number	468717201202
Result	✓ Passed

- Notice** Screen has various small chips on it
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nail in nearside rear tyre
- Notice** Front discs corroding
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear discs in poor condition

**MOT #3**

2011-07-26 12:24

**MOT test number**

677197601224

**Result****✗ Failed**

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Rear discs in poor condition
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Screen has various small chips on it
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Notice** Nail in nearside rear tyre
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Front discs corroding
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #2**

2010-08-10 11:18

**MOT test number**

472622020269

**Result****✓ Passed**

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Notice** Front brake discs corroded more the o/s/ one
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #1**

2009-07-27 13:14

**MOT test number**

651268809210

**Result****✓ Passed**



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
5 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	5 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GR06RXW
Plate since	2019-09-29
Current registration	GR06RXW
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-07-31
Last registration	2023-08-01
Complete history	<a href="#">See info</a>



Registration #1	2006-07-31	17 mi
Registration #2	2009-07-27	17.206 mi
Registration #3	2010-08-10	29.622 mi
Registration #4	2011-07-26	38.883 mi
Registration #5	2011-07-26	38.883 mi
Registration #6	2012-07-17	51.287 mi
Registration #7	2012-07-17	51.287 mi
Registration #8	2013-08-16	62.208 mi
Registration #9	2014-08-14	75.135 mi
Registration #10	2014-08-15	75.138 mi
Registration #11	2015-08-11	87.748 mi
Registration #12	2015-08-11	87.757 mi
Registration #13	2015-08-11	87.757 mi
Registration #14	2015-08-11	87.757 mi
Registration #15	2015-08-11	87.757 mi
Registration #16	2015-08-11	87.757 mi
Registration #17	2015-08-11	87.757 mi
Registration #18	2015-08-11	87.757 mi
Registration #19	2015-08-11	87.757 mi
Registration #20	2015-08-11	87.757 mi
Registration #21	2015-08-11	87.757 mi
Registration #22	2015-08-11	87.757 mi
Registration #23	2015-08-11	87.757 mi

More info >





Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Number of seats	5
Engine number	NOT KNOWN