





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|--------------------|
| Model | KUGA TITANIUM TDCI |
| Colour | White |
| Year of manufacture | 2010 |
| Top speed | 122 mph |
| 0 - 60 mph | 9.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 138 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 3.250 rpm |
| Engine capacity | 1.997 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 57.6 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 159 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/12



Internet history

Entry 1

| Date | 2021-01-30 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk

CarCheck.co.uk page 2/12



✓ Passed

| M | | history |
|---|---|----------|
| | - | IIISLUIV |

Result

| MOT expiry date | 2024-11-13 |
|--------------------|------------------|
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 6 |
| MOT #13 | 2023-11-07 14:19 |
| MOT test number | 612314417324 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-13 |
| MOT #12 | 2022-11-03 13:22 |
| MOT test number | 566325654954 |

| MOT #11 | 2021-11-05 14:22 |
|-----------------|------------------|
| MOT test number | 613439646859 |
| Result | √ Passed |

| MOT #10 | 2020-11-14 14:14 |
|-----------------|------------------|
| MOT test number | 336495019594 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



SB100JU

report date: 2024-03-28

MOT #9 2020-10-27 15:55 **MOT** test number 247667489649 Result × Failed Fail Exhaust has a major leak of exhaust gases center exhaust (6.1.2 (a)) **Advice** Rear exhaust heat shield loose **Minor** Offside Rear Tyre obviously under inflated (5.2.3 (I)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Emissions not tested (8.2.2.2 (e)) Fail **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

MOT test number

191844612671

Result

✓ Passed

MOT #7

2018-06-30 08:23

MOT test number

656130960253

MOT #6 2018-06-27 13:25

MOT test number 338423689813

Result X Failed

Fail Nearside Rear Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Rear Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))

Fail Offside Front Position lamp not working (4.2.1 (a))

CarCheck.co.uk page 4/12



Result

SB100JU

report date: 2024-03-28

✓ Passed

MOT #5

MOT test number

Result

MOT #4

MOT test number

2017-06-07 16:37

762945145308

✓ Passed

2016-02-08 11:28

MOT test number

160505816732

Advice Offside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)

 MOT #3
 2015-01-26 14:58

 MOT test number
 185096925032

 Result
 ✓ Passed

MOT #2

MOT test number

Result

Notice Child seat fitted not allowing full inspection of adult belt

Advice Front Brake pad(s) wearing thin (3.5.1g)

| MOT #1 | 2013-07-03 12:37 |
|-----------------|------------------|
| MOT test number | 255834483448 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 337 |
| MOT expiry date | 13 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|-----------------------------------------|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 6/12



SB100JU

report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

SB100JU

report date: 2024-03-28

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2010-07-30 |
| Last registration | 2023-11-07 |
| Complete history | See info |



| Registration #1 | 2010-07-30 | 22 mi |
|------------------|------------|------------|
| Registration #2 | 2013-07-03 | 50.216 mi |
| Registration #3 | 2014-02-07 | 60.762 mi |
| Registration #4 | 2015-01-26 | 67.910 mi |
| Registration #5 | 2016-02-08 | 72.710 mi |
| Registration #6 | 2017-06-07 | 82.245 mi |
| Registration #7 | 2018-06-27 | 85.751 mi |
| Registration #8 | 2018-06-30 | 85.751 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 91,709 esi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91,709 esi |
| Registration #14 | | 11.777 es |
| Registration #15 | | D 377 au |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditionir |
|-------|-----------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1884 mm |
|---------------------|---------|
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Max. allowed weight | 2505 kg |

Additional information

| Fuel tank capacity | 70 |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Number of axles CarCheck.co.uk | 2 page 12/12 |

Engine number

AU21080