



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2013
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





MOT history

MOT expiry date	2025-04-17
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	37
Total items failed	2

MOT #12	2024-04-18 16:00
MOT test number	310432849648
Result	✓ Passed
Next expiry date	2025-04-17

MOT #11	2024-04-18 15:34
MOT test number	654855333978
Result	✗ Failed
MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #10	2023-04-13 13:02
MOT test number	731360717959
Result	✓ Passed
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

**MOT #9**

2023-04-01 10:07

MOT test number

571257585072

Result**✗ Failed****Advice**

Offside Front Side repeater slightly discoloured (4.4.3 (a))

Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR

Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MAJOR

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #8

2022-04-04 13:31

MOT test number

335419347423

Result**✓ Passed****Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Smell of diesel but no leaks found

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7

2021-03-22 14:54

MOT test number

988455922040

Result**✓ Passed****Advice**

Rear Coil spring corroded O/S and N/S (5.3.1 (b) (i))

Advice

Bonnet primary retaining device slightly deteriorated (3.1 (c))

Minor

Front Anti-roll bar linkage ball joint dust cover severely deteriorated O/S and N/S (5.3.4 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #6**

2020-11-24 16:35

MOT test number

504359457930

Result

✓ Passed

- Advice** N/S/F anti roll bar link ball joint rubber perishing
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** O/S/F anti roll bar link ball joint rubbers perishing
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5

2020-11-23 14:04

MOT test number

910697947998

Result

✗ Failed

- Advice** N/S/F anti roll bar link ball joint rubber perishing
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- DANGEROUS** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** O/S/F anti roll bar link ball joint rubbers perishing
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- DANGEROUS** Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #4**

2019-05-20 13:07

MOT test number

618424918986

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Under trays fitted limiting underside view
- Advice** O/S/F tyre on 4mm tread
- Advice** N/S/R tyre wearing on inner edges
- Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil Leak
- Advice** N/S/F tyre on 3mm tread

MOT #3

2017-11-20 08:29

MOT test number

317845962014

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit wearing on inner edge (4.1.E.1)

MOT #2

2016-09-05 12:56

MOT test number

771572462920

Result

✓ Passed

MOT #1

2016-09-05 12:56

MOT test number

752225627437

Result

✗ Failed

- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
17 April 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-05
Last registration	2024-04-18
Complete history	See info



Registration #1	2013-09-05	14 mi
Registration #2	2016-09-05	49.610 mi
Registration #3	2016-09-05	49.610 mi
Registration #4	2017-11-20	64.378 mi
Registration #5	2019-05-20	69.122 mi
Registration #6	2020-11-23	76.621 mi
Registration #7	2020-11-24	76.659 mi
Registration #8	2020-11-24	76.659 mi
Registration #9	2020-11-24	76.659 mi
Registration #10	2020-11-24	76.659 mi
Registration #11	2020-11-24	76.659 mi
Registration #12	2020-11-24	76.659 mi
Registration #13	2020-11-24	76.659 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	4945767