



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX ZETEC 145
Colour	Silver
Year of manufacture	2008
Top speed	119 mph
0 - 60 mph	11.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-02
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-10-09
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	26
Total items failed	11

MOT #15	2020-10-08 08:25
---------	------------------

MOT test number	398276879926
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2021-10-09
------------------	------------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases centre pipe to rear sleeve section (6.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #14**

2020-10-06 09:25

MOT test number

910697952909

Result

✗ Failed

Advice Exhaust has a minor leak of exhaust gases centre pipe to rear sleeve section (6.1.2 (a))**Minor** Nearside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brake disc significantly and obviously worn both sides (1.1.14 (a) (i))**Fail** Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen washer not working (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Outer Tyre has ply or cords exposed sidewall (5.2.3 (d) (ii))**MOT #13**

2019-10-03 09:05

MOT test number

570429470662

Result

✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened both worn and pitted on inner faces (1.1.14 (a) (ii))**MOT #12**

2018-10-10 10:12

MOT test number

746078298889

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**MOT #11** 2017-08-23 10:23**MOT test number** 468339147524**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Near side rear tyre on 3mm**MOT #10** 2017-08-23 10:23**MOT test number** 672678001991**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Near side rear tyre on 3mm**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #9** 2016-08-09 10:25**MOT test number** 218232367000**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**Advice** Front wipers poor**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-08-10 11:39**MOT test number** 987342925281**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #7** 2014-07-31 14:07**MOT test number** 337482114267**Result** ✓ Passed**MOT #6** 2014-07-31 09:57**MOT test number** 307052514405**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-08-16 16:45**MOT test number** 177018423223**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2013-08-16 13:24**MOT test number** 188628023266**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #3** 2012-11-19 16:27**MOT test number** 228194622310**Result** ✓ Passed



MOT #2	2012-05-31 12:40
MOT test number	838622952126
Result	✓ Passed

MOT #1	2011-09-01 15:43
MOT test number	725504341252
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
13 August 2021

✕
MOT

Expired:
9 October 2021

Tax status	Expired at 13 August 2021
Days left	990 days too late
MOT expiry date	9 October 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-18
Last registration	2020-10-08
Complete history	See info



Registration #1	2008-09-18	6 mi
Registration #2	2011-09-01	14.933 mi
Registration #3	2012-05-31	20.632 mi
Registration #4	2012-11-19	24.604 mi
Registration #5	2013-08-16	30.024 mi
Registration #6	2013-08-16	30.024 mi
Registration #7	2014-07-31	40.588 mi
Registration #8	2014-07-31	40.588 mi
Registration #9	2015-08-10	51.870 mi
Registration #10	2015-08-10	51.870 mi
Registration #11	2015-08-10	51.870 mi
Registration #12	2015-08-10	51.870 mi
Registration #13	2015-08-10	51.870 mi
Registration #14	2015-08-10	51.870 mi
Registration #15	2015-08-10	51.870 mi
Registration #16	2015-08-10	51.870 mi
Registration #17	2015-08-10	51.870 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1435 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7M32473