



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Silver
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	313 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.7 mpg





Internet history

Entry 2

Date	2021-07-19
Pictures	2
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-18
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #21	2022-06-30 10:37
MOT test number	454690600141
Result	✓ Passed
Next expiry date	2023-07-14
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #20	2022-06-30 10:37
MOT test number	482190126807
Result	✗ Failed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))



MOT #19	2021-07-15 09:01
MOT test number	256228046335
Result	✓ Passed
Advice	Sill covers fitted
Advice	Welding repairs undersealed

MOT #18	2021-07-13 10:46
MOT test number	472431580303
Result	✗ Failed
Advice	Rear Brake hose slightly deteriorated x2 (1.1.12 (b) (ii))
Advice	Extent of corrosion to outer sills cannot be checked until sill covers are removed
Fail	Nearside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced inner/outer sill (6.1.1 (c) (i))
Fail	Nearside Front Anti-roll bar pin or bush likely to become detached droplink (5.3.4 (a) (ii))
Advice	Brake pipe corroded, covered in grease or other material all pipes (1.1.11 (c))
Fail	Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill/under plastic trim (7.1.1 (a) (i))
Fail	Offside Front Anti-roll bar pin or bush likely to become detached droplink (5.3.4 (a) (ii))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #17	2020-10-05 11:03
MOT test number	642949734035
Result	✓ Passed

MOT #16	2019-11-08 13:57
MOT test number	227636709679
Result	✓ Passed



MOT #15	2018-12-13 12:08
MOT test number	881579673608
Result	✓ Passed
MOT #14	2018-01-08 13:04
MOT test number	856049141099
Result	✓ Passed
MOT #13	2017-01-16 09:17
MOT test number	488199806135
Result	✓ Passed
MOT #12	2016-01-08 09:15
MOT test number	627653955455
Result	✓ Passed
MOT #11	2015-01-19 09:37
MOT test number	235259515070
Result	✓ Passed
MOT #10	2014-01-23 08:39
MOT test number	589463424089
Result	✓ Passed
MOT #9	2013-01-18 09:26
MOT test number	169538013002
Result	✓ Passed



MOT #8 2012-01-20 09:42

MOT test number 666000622006

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Airbag light on
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2011-01-21 09:48

MOT test number 136531021428

Result ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #6 2011-01-21 09:48

MOT test number 156731121072

Result ✗ Failed

- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Pass with rectification** Nearside Stop lamp not working (1.2.1b)

MOT #5 2010-01-05 09:42

MOT test number 183425100026

Result ✓ Passed

MOT #4 2009-01-07 11:21

MOT test number 804737109001

Result ✓ Passed



MOT #3 2008-01-08 10:11

MOT test number 473318708001

Result ✓ Passed

MOT #2 2007-01-09 12:30

MOT test number 790619507015

Result ✓ Passed

MOT #1 2007-01-08 09:58

MOT test number 784958907003

Result ✗ Failed

Fail Offside Headlamp aim beam image kick up to the offside (1.8)

Notice Flight damage to ns front tyre sidewall

Fail Brake linkage has restricted free movement (3.5.1k)




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check

 If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YX11 X
Plate since	2019-03-29
Current registration	YX11 X
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-01-24
Last registration	2022-06-30
Complete history	See info



Registration #1	2004-01-24	12 mi
Registration #2	2007-01-08	21.582 mi
Registration #3	2007-01-09	21.584 mi
Registration #4	2008-01-08	25.660 mi
Registration #5	2009-01-07	29.434 mi
Registration #6	2010-01-05	31.839 mi
Registration #7	2011-01-21	34.035 mi
Registration #8	2012-01-20	35.097 mi
Registration #9	2013-01-18	37.050 mi
Registration #10	2014-01-23	39.330 mi
Registration #11	2015-01-19	41.660 mi
Registration #12	2016-01-08	44.012 mi
Registration #13	2016-01-08	44.012 mi
Registration #14	2016-01-08	44.012 mi
Registration #15	2016-01-08	44.012 mi
Registration #16	2016-01-08	44.012 mi
Registration #17	2016-01-08	44.012 mi
Registration #18	2016-01-08	44.012 mi
Registration #19	2016-01-08	44.012 mi
Registration #20	2016-01-08	44.012 mi
Registration #21	2016-01-08	44.012 mi
Registration #22	2016-01-08	44.012 mi
Registration #23	2016-01-08	44.012 mi

[More info >](#)



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2079 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	D4CB3 630518