

Ford



### General information

| Make                | FORD                              |
|---------------------|-----------------------------------|
| Model               | GRAND C-MAX GRAND TITANIUM X TDCI |
| Colour              | Silver                            |
| Year of manufacture | 2012                              |
| Gearbox             | 6 speed Manual                    |

# Engine & fuel consumption

| Power           | 161 BHP  | 0 < 101 A                           |
|-----------------|----------|-------------------------------------|
| Engine capacity | 1.997 cc | 101 - 120 <sup>B</sup> <sub>C</sub> |
| Cylinders       | 4        | 121 - 140 E                         |
| Fuel type       | Diesel   | 141 - 165 F G                       |
| CO2 emission    | 134 g/km | 166 - 185                           |
| CO2 label       | E        | 186 - 225 J                         |
|                 |          | 225+ L                              |





# Internet history

Entry 1

Date

2021-06-16

Pictures

5

Listing price

View report



source: autotrader.co.uk



# MOT history

| MOT expiry date    | 2024-06-20 |
|--------------------|------------|
| MOT pass rate      | 82 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 2          |
| Total advice items | 15         |
| Total items failed | 2          |

| MOT #11   |   | 2023-06-13 08:55     |
|-----------|---|----------------------|
| MOT test  | number  | 251231778310         |
| Result    |   | ✓ Passed             |
| Next expi | ry date   | 2024-06-20           |
| Advice    | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords | (5.2.3 (d) (i))      |
| Advice    | Front Registration plate damaged but not likely to be misread             |                      |
| Advice    | Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))               |                      |
| Advice    | Offside Front Road wheel slightly distorted (5.2.2 (c) (i))               |                      |
| Advice    | Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly | worn (5.1.2 (b) (i)) |

| MOT #10    | 2022-05-23 10   | :09  |
|------------|---|------|
| MOT test i | number 8017705129   | 946  |
| Result     | ✓ Pas   | sed  |
| Advice     | Suspension arm pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) | (i)) |
| Advice     | Offside Front Road wheel slightly distorted (5.2.2 (c) (i))                                   |      |
| Advice     | Axle swivel pins and bushes swivel pin and/or bush slightly worn Both rear (5.1.2 (b) (i))    |      |
| Advice     | Child Seat fitted not allowing full inspection of adult belt                                  |      |





| MOT #9   | 2021-06-21 11:25           |
|--|----------------------------|
| MOT test number  | 195752074949               |
| Result   | ✓ Passed                   |
| AdviceRear Suspension arm pin or bush worn but not resulting in excessive m<br>bushes (5.3.4 (a) (i))AdviceNearside Front chip in screen | novement both trailing arm |
| MOT #8   | 2020-10-02 14:40           |
| MOT test number  | 169511240799               |
| Result   | ✓ Passed                   |
| MOT #7   | 2019-12-12 16:13           |
| MOT test number  | 723782806261               |

| Result                 | ✓ Passed  |
|------------------------|---|
| Advice<br>(i))         | Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) |
| <b>Advice</b> (a) (i)) | Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4    |

| МОТ #6          | 2018-12-18 14:32 |
|-----------------|------------------|
| MOT test number | 155333846150     |
| Result          | ✓ Passed         |

| MOT #5  | 2018-12-14 16:42 |
|---|------------------|
| MOT test number   | 133312351543     |
| Result  | 🗙 Failed         |
| Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i)) |                  |

| MOT #4                  |  | 2017-12-15 17:15          |
|-------------------------|--|---------------------------|
| MOT test                | number   | 249088974504              |
| Result                  |  | ✓ Passed                  |
| <b>Advice</b> (2.4.G.2) | Nearside Rear Trailing arm rubber bush deteriorated but not result | ing in excessive movement |





| MOT #3   | 2017-12-15 17:15 |  |
|--|------------------|--|
| MOT test number  | 298437234208     |  |
| Result   | 🗙 Failed         |  |
| Pass with rectificationNearside Stop lamp not working (1.2.1b)   |                  |  |
| Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) |                  |  |
| MOT #2   | 2016-12-15 09:20 |  |
| MOT test number  | 639695387893     |  |
| Result   | Passed           |  |
|  |                  |  |
| MOT #1   | 2015-11-30 10:23 |  |
| MOT test number  | 950477472902     |  |
| Result   | ✓ Passed         |  |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 June 2024 | ✓<br>MOT<br>Expires:<br>20 June 2024 |
|---------------------------------------|--------------------------------------|
| Tax status                            | Valid until 1 June                   |
| Days left                             | 33                                   |
| MOT expiry date                       | 20 June 2024                         |
| Full MOT history                      | See MOT history                      |

### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |       |
|----------|-------|
| Date     |       |
| Category | Lamp  |
| Туре     |       |
| Damage 2 | AMPL  |
| Damage 2 | E COL |
| Date     | S.    |
| Category | ame   |
| Туре     |       |

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| ************   |             |
| ********   |             |
| ******   |             |
| ************   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FORD had different number plates.  |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 13         |
| First mileage registration | 2012-12-24 |
| Last registration          | 2023-06-13 |
| Complete history           | See info   |



| Registration #1  | 2012-12-24 | 10 mi      |
|------------------|------------|------------|
| Registration #2  | 2015-11-30 | 37.562 mi  |
| Registration #3  | 2016-12-15 | 51.170 mi  |
| Registration #4  | 2017-12-15 | 66.822 mi  |
| Registration #5  | 2017-12-15 | 66.822 mi  |
| Registration #6  | 2018-12-14 | 82.003 mi  |
| Registration #7  | 2018-12-18 | 82.094 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.777 esi |
| Registration #12 |            | 11.777 est |
| Registration #13 |            | 11.777 mi  |

More info >





### Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| S0482  |                  |
| \$0501 |                  |
| S0566  |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 96%             |
| Children       | 81%             |
| Pedestrian     | 50%             |
| Safety systems | 71%             |
| Overall rating | 81%             |
| Video          | see crash video |



| Dimensions & weight    |                  |
|------------------------|------------------|
| Width                  | 2067 mm          |
| Height                 | 1698 mm          |
| Length                 | 4520 mm          |
| Kerb weight            | 1575 kg          |
| Max. allowed weight    | 2300 kg          |
| Additional information |                  |
| Fuel delivery          | Direct Injection |

| Fuel delivery   | Direct Injection |
|-----------------|------------------|
| Number of doors | 5                |
| Number of seats | 7                |
| Engine number   | CT66178          |