



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 ACTIVE AWD
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.4 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





MOT history

MOT expiry date	2021-10-08
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	15
Total items failed	4

MOT #11	2020-10-09 14:17
MOT test number	664168141522
Result	✓ Passed
Next expiry date	2021-10-08

MOT #10	2020-10-07 15:28
MOT test number	310003585940
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Central Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9	2019-09-20 07:52
MOT test number	796742517033
Result	✓ Passed

MOT #8	2019-09-20 07:52
MOT test number	655621648337
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #7** 2018-09-13 07:46**MOT test number** 339263042963**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively nearside offside (1.1.14 (a) (i))**MOT #6** 2018-09-13 07:46**MOT test number** 827450292562**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Front Brake disc worn, but not excessively nearside offside (1.1.14 (a) (i))**MOT #5** 2017-09-08 10:17**MOT test number** 987225172809**Result** ✓ Passed**Advice** Under trays engine covers fitted obscuring some items**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #4**

2016-09-14 09:48

MOT test number

504488516696

Result

✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Under trays engine covers fitted obscuring some items
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

2015-09-14 13:08

MOT test number

827476918617

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

2014-04-10 14:54

MOT test number

507740104130

Result

✓ Passed

MOT #1

2013-04-04 11:31

MOT test number

407844893090

Result

✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 August 2021

✕
MOT

Expired:
8 October 2021

Tax status	Expired at 31 August 2021
Days left	971 days too late
MOT expiry date	8 October 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-03-23
Last registration	2020-10-09
Complete history	See info



Registration #1	2010-03-23	25 mi
Registration #2	2013-04-04	27.446 mi
Registration #3	2014-04-10	43.046 mi
Registration #4	2015-09-14	61.027 mi
Registration #5	2016-09-14	76.422 mi
Registration #6	2017-09-08	93.125 mi
Registration #7	2018-09-08	109.828 mi
Registration #8	2019-09-08	126.531 mi
Registration #9	2020-09-08	143.234 mi
Registration #10	2021-09-08	159.937 mi
Registration #11	2022-09-08	176.640 mi
Registration #12	2023-09-08	193.343 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2130 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

784551