



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Black
Year of manufacture	2012
Top speed	127 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.5 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 2


Date	2022-04-02
Pictures	5
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-05-29
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-29
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	21
Total items failed	3

MOT #15	2023-04-04 09:27
MOT test number	786681528494
Result	✓ Passed
Next expiry date	2024-04-29
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14	2022-04-30 10:57
MOT test number	354007721269
Result	✓ Passed

MOT #13	2021-09-22 06:37
MOT test number	734109255569
Result	✓ Passed

MOT #12	2021-05-12 08:27
MOT test number	261830590897
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2020-05-26 10:00
MOT test number	906799221698
Result	✓ Passed

**MOT #10** 2020-05-26 10:00**MOT test number** 982228731848**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #9** 2019-12-18 15:36**MOT test number** 772892532913**Result** ✓ Passed**MOT #8** 2019-12-18 09:53**MOT test number** 890416064527**Result** ✗ Failed**MAJOR** Nearside Rear Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MAJOR** Front Windscreen washer not working (3.5 (a))**MOT #7** 2019-05-29 11:48**MOT test number** 210242499184**Result** ✓ Passed**MOT #6** 2019-05-29 10:31**MOT test number** 501340200272**Result** ✗ Failed**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #5** 2018-05-24 11:59**MOT test number** 153070133119**Result** ✓ Passed**Advice** Nearside Rear tyre wearing uneven outer**Advice** Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4**

2017-06-02 11:57

MOT test number

582454748593

Result

✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner surface of disc slightly corroded (3.5.1i)

Advice Rear rear handbrake efficiency just passed 17%

Advice Offside Front Brake pad(s) modified but not seriously weakened os/f inner pad 3mm, inner surface of disc slightly corroded (3.5.1n)

MOT #3

2017-05-31 11:41

MOT test number

936633992383

Result

✗ Failed

Advice Nearside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner surface of disc slightly corroded (3.5.1i)

Fail Offside Front Tyre tread depth below requirements of 1.6mm 1 mm (4.1.E.1)

Advice Offside Front Brake pad(s) modified but not seriously weakened os/f inner pad 3mm, inner surface of disc slightly corroded (3.5.1n)

Fail Electronic stability system warning lamp indicates a fault (3.4.1c)

Advice Rear rear handbrake efficiency just passed 17%

MOT #2

2016-05-19 14:08

MOT test number

586021905033

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #12015-05-20 10:29

MOT test number896570045167

Result

✓ Passed

AdviceRear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

AdviceOffside Front Tyre worn close to the legal limit (4.1.E.1)

NoticeVery slight signs of greese from offside front cv joint leak from clip area

AdviceNearside Front Tyre worn close to the legal limit (4.1.E.1)

NoticeNearside front tyre wearing low on outer edge



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
29 April 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-01-06
Last registration	2023-04-04
Complete history	See info



Registration #1	2012-01-06	23 mi
Registration #2	2015-05-20	11.645 mi
Registration #3	2016-05-19	19.794 mi
Registration #4	2017-05-31	29.387 mi
Registration #5	2017-06-02	29.388 mi
Registration #6	2018-05-24	37.756 mi
Registration #7	2019-05-29	44.762 mi
Registration #8	2019-05-29	44.762 mi
Registration #9	2019-12-18	47.873 mi
Registration #10	2019-05-29	44.762 mi
Registration #11	2019-05-29	44.762 mi
Registration #12	2019-05-29	44.762 mi
Registration #13	2019-05-29	44.762 mi
Registration #14	2019-05-29	44.762 mi
Registration #15	2019-05-29	44.762 mi
Registration #16	2019-05-29	44.762 mi
Registration #17	2019-05-29	44.762 mi
Registration #18	2019-05-29	44.762 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2112 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1139303