





report date: 2024-03-28

#### General information

Make	RENAULT
Model	CAPTUR EXPRESSIONPLUS CONVENIENCE ENERGYTCE S/S
Colour	Black
Year of manufacture	2013
Top speed	106 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28


## Internet history

#### Entry 1

Date 2021-01-21

Pictures 33

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-17
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #9		2023-11-15 14:37
MOT test	number	589119635489
Result		✓ Passed
Next expi	ry date	2024-11-17
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre wearing on edges	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2022-11-16 08:51
MOT test number	705448725417
Result	<b>✓</b> Passed
MOT #7	2021-10-20 08:35
MOT test number	890922889308
Result	<b>✓</b> Passed
MOT #6	2020-10-29 16:00
MOT test number	970083175684
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



Advice

**HV63FDY** 

report date: 2024-03-28

 MOT #5
 2019-10-21 08:46

 MOT test number
 583703010124

 Result
 ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking between treads (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking between treads (5.2.3 (d) (ii))

MOT test number

Fass with rectification

Nearside Headlamp aim too low (4.1.2 (a))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing cracking between treads (5.2.3 (d) (ii))

Pass with rectification

Offside Headlamp aim too low (4.1.2 (a))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing cracking between treads (5.2.3 (d) (ii))

MOT #3

MOT test number

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

2018-10-26 07:59

512912418700

Passed

Passed

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Front Brake disc worn, but not excessively both front discs worn and lipped (1.1.14 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2		2017-10-25 10:11
MOT test	number	393766048671
Result		✓ Passed
Advice	Coolant level low	
Advice	Advice Front Brake pad(s) wearing thin o/s & n/s (3.5.1g)	
Advice	Child Seat fitted not allowing full inspection of adult belt X2	

MOT #1		2016-11-10 09:20
MOT test	number	861077528378
Result		<b>✓</b> Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front wheel arch guard out of shape	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check





Expires: 17 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	17 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full		ULT
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-11-18
Last registration	2023-11-15
Complete history	See info



Registration #1	2013-11-18	17 mi
Registration #2	2016-11-10	24.283 mi
Registration #3	2017-10-25	29.016 mi
Registration #4	2018-10-26	34.434 mi
Registration #5	2019-10-21	40.813 mi
Registration #6	2019-10-21	40.813 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



## Dimensions & weight

Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1089 kg
Max. allowed weight	1663 kg

### Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1.	2/12

Number of axles 2

Engine number D019057