





report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO 850 ENTERPRISE L1 BLUEHDI
Colour	Black
Year of manufacture	2018
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2024-09-26
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	17
Total items failed	5

MOT #4	2023-09-27 14:19
MOT test number	466945004110
Result	✓ Passed
Next expiry date	2024-09-26
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	le lamps or light sources

MOT #3		2022-10-18 13:44
MOT test	number	167008413545
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin On both sides (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing Tread (5.2.3 (d) (ii))	
Advice	Items removed from driver's view prior to test	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/10



LD68WDJ

report date: 2024-03-28

MOT #2 2022-10-18 09:28

MOT test number 661771607568

Result X Failed

Advice Rear Brake pad(s) wearing thin On both sides (1.1.13 (a) (ii))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Direction indicator slightly discoloured Both (4.4.3 (a))

Advice Items removed from driver's view prior to test

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt lower dust cover (5.3.4 (b) (ii))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Advice Offside Front Tyre slightly damaged/cracking or perishing Tread (5.2.3 (d) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt lower dust cover (5.3.4 (b) (ii))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #1 2021-10-28 15:04

MOT test number 386942809421

Result ✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/10



Tax & MOT check



Tax statusValid until 1 JulyDays left64MOT expiry date26 September 2024Full MOT historySee MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 4/10




LD68WDJ

report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



LD68WDJ

report date: 2024-03-28

Owner	hictory
Owner	TIISLUTY

e when miscery		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		OEN
manuscope de la companya della companya della companya de la companya de la companya della compa		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 7/10



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2018-10-31
Last registration	2023-09-27
Complete history	See info



Registration #1	2018-10-31	25 mi
Registration #2	2021-10-28	43.293 mi
Registration #3	2022-10-18	78.910 mi
Registration #4		77.777 66
Registration #5		11.777 es

More info >

CarCheck.co.uk page 9/10



Safety ratings

NCAP rating	****
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBHB3279953

CarCheck.co.uk page 10/10