




report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Grey
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-08
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	15
Total items failed	8

MOT #17	2023-06-09 11:32
MOT test number	525865734700
Result	✓ Passed
Next expiry date	2024-06-08

MOT #16	2022-04-07 14:13
MOT test number	647386297059
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-04-04 12:56
MOT test number	567619374826
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Rear Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #14** 2021-04-21 15:48**MOT test number** 728069086512**Result** ✓ Passed**MOT #13** 2021-04-21 13:26**MOT test number** 468943630748**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12** 2020-06-01 14:27**MOT test number** 326002800393**Result** ✓ Passed**MOT #11** 2020-06-01 09:12**MOT test number** 726243221377**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))**MOT #10** 2019-05-30 09:19**MOT test number** 717578007826**Result** ✓ Passed**MOT #9** 2019-05-24 13:50**MOT test number** 143702698512**Result** ✗ Failed**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #8** 2018-05-29 11:45**MOT test number** 569228074795**Result** ✓ Passed**MOT #7** 2017-06-05 10:10**MOT test number** 165478001675**Result** ✓ Passed**MOT #6** 2017-06-02 13:59**MOT test number** 804441244717**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #5** 2016-05-25 12:23**MOT test number** 310398455057**Result** ✓ Passed**MOT #4** 2015-06-15 09:17**MOT test number** 218366865436**Result** ✓ Passed**MOT #3** 2014-06-10 14:36**MOT test number** 298491564167**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Both rear bump stops worn**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #2	2013-06-10 14:04
MOT test number	247291263178
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2013-05-29 17:01
MOT test number	569399743142
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Fail	Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
8 June 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-12
Last registration	2023-06-09
Complete history	See info



Registration #1	2010-06-12	13 mi
Registration #2	2013-05-29	47.762 mi
Registration #3	2013-06-10	48.010 mi
Registration #4	2014-06-10	64.999 mi
Registration #5	2015-06-15	85.401 mi
Registration #6	2016-05-25	92.102 mi
Registration #7	2017-06-02	98.120 mi
Registration #8	2017-06-05	98.132 mi
Registration #9	2018-05-29	101.165 mi
Registration #10	2019-05-24	106.816 mi
Registration #11	2020-05-29	111.467 mi
Registration #12	2021-05-29	116.118 mi
Registration #13	2022-05-29	120.769 mi
Registration #14	2023-05-29	125.420 mi
Registration #15	2024-05-29	130.071 mi
Registration #16	2025-05-29	134.722 mi
Registration #17	2026-05-29	139.373 mi
Registration #18	2027-05-29	144.024 mi
Registration #19	2028-05-29	148.675 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1895 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	848865