






report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO R LINE TDI BLUEMOTION TECHNOLO
Colour	Blue
Year of manufacture	2016
Top speed	134 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	320 Nm at 3.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2023-06-05

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2023-05-25


Pictures 49

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date 2021-11-05

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-06-02
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #5	2023-06-03 11:45
MOT test number	587530393487
Result	✓ Passed
Next expiry date	2024-06-02
Advice Front Coil spring corroded both (5.3.1 (b) (i))	

MOT #4	2022-11-11 11:43
MOT test number	591422276127
Result	✓ Passed
MOT #3	2021-11-11 12:53
MOT test number	528436815372
Result	✓ Passed
MOT #2	2021-01-25 14:47

		0_0.000_007_
Result		✓ Passed
MOT #2		2021-01-25 14:47
MOT test	number	488641392342
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)) (ii))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		

CarCheck.co.uk page 3/11



(ii))

NY16CVJ report date: 2024-03-28

MOT #1 2019-07-29 14:19

MOT test number 177817014798

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a)

Advice Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	2 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Damage 2

Type

Date

Category
Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK OK
Plate since	

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-07-29
Last registration	2023-06-03
Complete history	See info



Registration #1	2016-07-29	26 mi
Registration #2	2019-07-29	29.043 mi
Registration #3	2021-01-25	41.927 mi
Registration #4		71.777 66
Registration #5	2021-11-11	49.852 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		71.777 66
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2080 mm
Height	1406 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1275 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	3
Number of axles	2

CarCheck.co.uk page 11/11