



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 300 C/C SRW
Colour	Green
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	330 Nm at 1.350 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-20
Pictures	30
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-11
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	25
Total items failed	19

MOT #14	2023-06-12 15:28
MOT test number	695148234808
Result	✓ Passed
Next expiry date	2024-06-11
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2023-06-12 13:46

MOT test number

740022251155

Result**✗ Failed**

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2022-05-17 14:27

MOT test number

467649296175

Result**✓ Passed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords long and deep, not to cords-Dangerous (5.2.3 (d) (i))
- Advice** Offside Front tyre has slight damage to outer sidewall.

**MOT #11**

2022-05-16 15:44

MOT test number

111489806202

Result

✗ Failed

- Fail** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Valve stem seriously damaged (5.2.3 (j))
- Advice** Offside Front tyre has slight damage to outer sidewall.
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords long and deep, not to cords-Dangerous (5.2.3 (d) (i))
- Fail** Nearside Front Valve stem seriously damaged (5.2.3 (j))
- Fail** Offside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush (5.3.4 (a) (i))

MOT #10

2021-05-15 11:55

MOT test number

451224130697

Result

✓ Passed

- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

MOT #9

2020-04-08 13:52

MOT test number

573623826497

Result

✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8** 2020-04-08 13:52**MOT test number** 388573431253**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #7** 2019-03-27 10:47**MOT test number** 499331188969**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #6** 2018-02-24 13:30**MOT test number** 950066632355**Result** ✓ Passed**MOT #5** 2018-02-23 17:11**MOT test number** 792350232870**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2017-02-10 16:47**MOT test number** 188458454768**Result** ✓ Passed

**MOT #3** 2016-02-12 16:55**MOT test number** 252841144366**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-02-14 13:35**MOT test number** 377455445031**Result** ✓ Passed**MOT #1** 2015-02-14 08:07**MOT test number** 968895945007**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
11 June 2024

Tax status	Valid until 1 September
------------	-------------------------

Days left	126
-----------	-----

MOT expiry date	11 June 2024
-----------------	--------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-01
Last registration	2023-06-12
Complete history	See info



Registration #1	2012-03-01	23 mi
Registration #2	2015-02-14	51.035 mi
Registration #3	2015-02-14	51.035 mi
Registration #4	2016-02-12	79.604 mi
Registration #5	2017-02-10	109.802 mi
Registration #6	2018-02-23	138.314 mi
Registration #7	2018-02-24	138.314 mi
Registration #8	2019-03-27	154.016 mi
Registration #9	2020-06-20	25,277 mi
Registration #10	2020-06-20	25,277 mi
Registration #11	2020-06-20	25,277 mi
Registration #12	2020-06-20	25,277 mi
Registration #13	2020-06-20	25,277 mi
Registration #14	2020-06-20	25,277 mi
Registration #15	2020-06-20	25,277 mi
Registration #16	2020-06-20	25,277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	CB27426