






report date: 2024-03-29

### General information

Make	VOLVO
Model	XC40 D3 MOMENTUM
Colour	Silver
Year of manufacture	2019
Top speed	124 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	47.9 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/10



## Internet history

#### Entry 1

Date	2022-06-03	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/10



GN19JZE

report date: 2024-03-29

## MOT history

MOT #2

MOT expiry date	2025-04-02
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	2
Total items failed	1

MOT #4	2024-04-02 13:22
MOT test number	698772647651
Result	✓ Passed
Next expiry date	2025-04-02

MOT #3	2023-03-23 13:35
MOT test number	895072644032
Result	✓ Passed

1101 // 2	
MOT test number 24	43237327573

**Result** X Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1	2022-03-30 07:39
MOT test number	349453153735
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/10



## Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	2 April 2025
Full MOT history	See MOT history

### Tax calculation

1 10 10 1	
Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

e when miscory	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
***************************************	
***********	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 7/10



### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-04-03
Last registration	2024-04-02
Complete history	See info



Registration #1	2019-04-03	11 mi
Registration #2	2022-03-30	32.947 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		n.m-

More info >

CarCheck.co.uk page 9/10



## Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	97%
Children	87%
Pedestrian	71%
Safety systems	76%
Overall rating	86%
Video	see crash video



# Dimensions & weight

Width	1910 mm
Height	1658 mm
Length	4425 mm
Max. allowed weight	2120 kg

## Additional information

Number of seats	5
Number of axles	2
Engine number	3194320

CarCheck.co.uk page 10/10