



PEUGEOT

LIG9849

report date: 2024-03-28

General information

Make	PEUGEOT
Model	EXPERT TEPEE COMFORT L1 HDI 90 6STR
Colour	Silver
Year of manufacture	2008
Top speed	90 mph
0 - 60 mph	18.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	39.2 mpg
CO2 emission	191 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-20
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	26
Total items failed	5

MOT #19 2023-09-26 15:54

MOT test number 241224043136

Result ✓ Passed

Next expiry date 2024-10-20

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Passenger seat(s) missing at time of test
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Coolant leak
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #18 2022-10-13 07:47

MOT test number 226648744832

Result ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17** 2022-10-13 07:47**MOT test number** 392755276664**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #16** 2021-10-16 10:40**MOT test number** 931361866405**Result** ✓ Passed**MOT #15** 2020-10-21 14:30**MOT test number** 454390363360**Result** ✓ Passed**MOT #14** 2020-10-21 14:30**MOT test number** 694200679278**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #13** 2019-08-16 09:01**MOT test number** 488685436859**Result** ✓ Passed**MOT #12** 2018-08-14 11:20**MOT test number** 171910497496**Result** ✓ Passed**Advice** Chip in windscreen.

**MOT #11** 2018-08-10 08:34**MOT test number** 196655313139**Result** ✗ Failed**Advice** DPF heat shield loose**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Chip in windscreen.**Advice** Offside wing mirror cover missing.**MOT #10** 2017-07-13 11:06**MOT test number** 193638479846**Result** ✓ Passed**MOT #9** 2016-07-15 09:29**MOT test number** 397265714947**Result** ✓ Passed**MOT #8** 2015-07-02 12:26**MOT test number** 267593385169**Result** ✓ Passed**MOT #7** 2014-08-04 10:46**MOT test number** 617156114282**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2013-08-08 11:20**MOT test number** 376420623498**Result** ✓ Passed

**MOT #5** 2013-04-16 10:09**MOT test number** 686106203138**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #4 2012-04-18 11:20**MOT test number** 328859802139**Result** ✓ Passed

- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Tested under wet conditions

MOT #3 2012-04-18 11:20**MOT test number** 578109202161**Result** ✗ Failed

- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Tested under wet conditions

MOT #2 2011-05-05 12:27**MOT test number** 498325921157**Result** ✓ Passed

- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #1	2011-05-05 12:27
MOT test number	166475721153
Result	✗ Failed
Advice	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Pass with rectification	Front Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
20 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	20 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	19
First mileage registration	2008-06-23
Last registration	2023-09-26
Complete history	See info



Registration #1	2008-06-23	27 mi
Registration #2	2011-05-05	19.821 mi
Registration #3	2012-04-18	30.442 mi
Registration #4	2013-04-16	42.254 mi
Registration #5	2013-08-08	46.013 mi
Registration #6	2014-08-04	90.844 mi
Registration #7	2015-07-02	67.728 mi
Registration #8	2016-07-15	71.099 mi
Registration #9	2017-07-13	85.080 mi
Registration #10	2018-08-10	95.071 mi
Registration #11	2019-05-20	95.071 mi
Registration #12	2019-05-20	95.071 mi
Registration #13	2019-05-20	95.071 mi
Registration #14	2019-05-20	95.071 mi
Registration #15	2019-05-20	95.071 mi
Registration #16	2019-05-20	95.071 mi
Registration #17	2019-05-20	95.071 mi
Registration #18	2019-05-20	95.071 mi
Registration #19	2019-05-20	95.071 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1998 mm
Height	1934 mm
Length	4806 mm
Wheel base	3000 mm
Max. allowed weight	2683 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	JBAZ0025156