



UK

PEIIGYN

report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ2
Colour	Black
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	0
Listing price	View report

source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	8
Total items failed	4

MOT #13 2023-07-26 08:56

MOT test number 525787641995

Result ✓ Passed

Next expiry date 2024-07-29

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Both inner CV boots slight leak of grease

MOT #12 2023-07-26 08:56

MOT test number 392468259912

Result ✗ Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Both inner CV boots slight leak of grease

Pass with rectification Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))

MOT #11 2022-07-06 11:09

MOT test number 965932027735

Result ✓ Passed

MOT #10 2021-07-30 08:47

MOT test number 351004403174

Result ✓ Passed

**MOT #9** 2021-07-29 12:12**MOT test number** 920661473381**Result** ✗ Failed**Fail** Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))**MOT #8** 2020-02-24 11:19**MOT test number** 323908895294**Result** ✓ Passed**MOT #7** 2020-02-18 12:22**MOT test number** 809696518547**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))**MOT #6** 2019-02-28 16:01**MOT test number** 779895997590**Result** ✓ Passed**MOT #5** 2018-03-02 09:53**MOT test number** 581199321908**Result** ✓ Passed**MOT #4** 2017-02-22 11:05**MOT test number** 152107536824**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)



MOT #3	2016-03-03 11:46
MOT test number	270324064604
Result	✓ Passed
MOT #2	2015-03-04 15:00
MOT test number	288733065039
Result	✓ Passed
MOT #1	2014-02-27 11:58
MOT test number	335698154040
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
29 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-04
Last registration	2023-07-26
Complete history	See info



Registration #1	2011-03-04	9 mi
Registration #2	2014-02-27	12.730 mi
Registration #3	2015-03-04	14.811 mi
Registration #4	2016-03-03	16.925 mi
Registration #5	2017-02-22	18.722 mi
Registration #6	2018-03-02	22.170 mi
Registration #7	2019-02-28	25.709 mi
Registration #8	2020-02-18	28.560 mi
Registration #9	2020-05-20	29.277 mi
Registration #10	2020-05-20	29.277 mi
Registration #11	2020-05-20	29.277 mi
Registration #12	2020-05-20	29.277 mi
Registration #13	2020-05-20	29.277 mi
Registration #14	2020-05-20	29.277 mi
Registration #15	2020-05-20	29.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1412346