





report date: 2024-03-28

General information

Make	VOLVO	
Model	V60 D3 INSCRIPTION	
Colour	Black	
Year of manufacture	2017	
Top speed	130 mph	
0 - 60 mph	7.9 seconds	
Gearbox	6 speed automatic	

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2022-01-31

Pictures 26

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2022-01-27


Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-25
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	7
Total items failed	4

MOT #5	2024-01-03 09:05
MOT test number	852419595761
Result	✓ Passed
Next expiry date	2025-01-25
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #4	2023-01-10 12:01
MOT test number	608614750748
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #3	2023-01-09 09:10	
MOT test number	592627778807	
Result	X Failed	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))		
Fail Brake pedal anti-slip provision missing (1.1.2 (c))		
Fail Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1		
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Fail Nearside Headlamp aim not tested (4.1.2 (b))		

CarCheck.co.uk page 3/11



MOT #2 2022-01-26 07:44

MOT test number 406646641171

Result ✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Under body shields fitted

MOT #1 2020-12-04 13:30

MOT test number 194897340021

Result ✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



·

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	Moro info

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-11
Last registration	2024-01-03
Complete history	See info



Registration #1	2017-12-11	9 mi
Registration #2	2020-12-04	72.269 mi
Registration #3	2022-01-26	86.593 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

page 10/11 CarCheck.co.uk



report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1439 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles2Engine number1997496