





report date: 2024-03-29

General information

Make	FORD
Model	KUGA TITANIUM TDCI
Colour	Silver
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-11

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



YP590LA report date: 2024-03-29

MOT history

MOT expiry date	2024-06-21
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #14	2023-06-20 09:45
MOT test number	630147373174
Result	✓ Passed
Next expiry date	2024-06-21

MOT #13	2022-06-13 14:58	
MOT test number	341893536402	
Result	✓ Passed	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	4 (a) (ii))	

MOT #12	2021-06-22 13:19
MOT test number	531041365747
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #10 2020-10-01 08:41 **MOT** test number 762504808747 Result × Failed Fail Front Exhaust has a major leak of exhaust gases Flexi pipe (6.1.2 (a)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii)) Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) **Advice** Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

MOT test number

Result

Advice Exhaust has a minor leak of exhaust gases Front flexy (6.1.2 (a))

MOT #8

MOT test number

728208532034

Result

Advice Exhaust has a minor leak of exhaust gases Front flexy (6.1.2 (a))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

694197805012

Result

Advice Exhaust has a minor leak of exhaust gases Front flexy (6.1.2 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #6 2017-09-25 09:02 **MOT** test number 708079001455 Result ✓ Passed **MOT #5** 2016-09-24 08:43 **MOT** test number 733315262574 Result ✓ Passed **MOT #4** 2015-10-03 10:17 **MOT** test number 132508176449 Result ✓ Passed

MOT #3

MOT test number

816552784240

Result

Notice Nsr tyre has deep cuts to tread face

Advice Inner Front Brake pad(s) wearing thin (3.5.1g)

Notice Fuel tank/filler neck has residue around pipes cannot determine if fuel seepage??

MOT #2	2013-09-27 13:32
MOT test number	126180873288
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2012-10-08 17:11

MOT test number 367322482410

CarCheck.co.uk page 6/13





report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



YP590LA report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



YP590LA report date: 2024-03-29

Owner history

Owner history		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



YP59OLA report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13




YP590LA report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-09
Last registration	2023-06-20
Complete history	See info



Registration #1	2009-11-09	17 mi
Registration #2	2012-10-08	17.891 mi
Registration #3	2013-09-27	26.698 mi
Registration #4	2014-10-09	33.510 mi
Registration #5	2015-10-03	40.477 mi
Registration #6	2016-09-24	44.643 mi
Registration #7	2017-09-25	50.068 mi
Registration #8	2018-09-18	55.912 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 12/13



YP590LA report date: 2024-03-29

Car features

S0225	Air conditionir
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1842 mm
Height	1677 mm
Length	4443 mm
Kerb weight	1613 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	58
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

9R89811