





report date: 2024-03-28

General information

Make	MINI
Model	PACEMAN COOPER
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-03

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-01
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #9	2023-07-03 14:58
MOT test number	926595938022
Result	✓ Passed
Next expiry date	2024-08-01
Advice Rear brake pipes swollen at flexi hoses	

MOT #8	2022-07-06 14:26
MOT test number	579902066972
Result	✓ Passed
MOT #7	2021-07-30 10:59
MOT test number	329071926418
Result	✓ Passed
MOT #6	2020-07-08 12:54
MOT test number	811592267829
Result	√ Passed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5 2019-07-15 08:31

MOT test number 333950394463

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge nsr tyre worn heavily on edges (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge osf tyre worn heavily on inner an outer edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge osr tyre worn heavily on edges (5.2.3 (e))

MOT #4 2018-08-02 11:09

MOT test number 474713887591

MOT #3 2018-05-15 12:52

MOT test number 860037715894

Result \(\sqrt{Passed} \)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #2 2018-05-15 11:01

MOT test number 239966572234

Result X Failed

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #1 2017-05-16 12:43

MOT test number 647235865345

Result

Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners die Check it in the premium report and see all owner registrations. Download the full report is		

THE PROPERTY OF THE PROPERTY O		
	More info >	
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-06-24
Last registration	2023-07-03
Complete history	See info



Registration #1	2014-06-24	15 mi
Registration #2	2017-05-16	25.758 mi
Registration #3	2018-05-15	31.756 mi
Registration #4	2018-05-15	31.756 mi
Registration #5	2018-08-02	32.171 mi
Registration #6	2019-07-15	45.851 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles2Engine numberA712J684