






report date: 2024-03-29

General information

Make	FORD
Model	TOURNEO CONNECT GRAND ZETEC TDCI
Colour	Blue
Year of manufacture	2016
Top speed	102 mph
0 - 60 mph	13.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm
Engine capacity	1.499 сс
Cylinders	4
Fuel type	Diesel
Consumption city	57.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 3

Date 2023-12-12

Pictures 8









source: g3remarketing.co.uk


Entry 2

Date 2021-07-07

Pictures

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-06


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-08-04
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	6
Total items failed	2

MOT #7	023-07-19 13:43
MOT test number	570833260123
Result	✓ Passed
Next expiry date	2024-08-04
Advice Front Tyre slightly damaged/cracking or perishing both sides front tyres (5.2.3 (d) (i	ii))

MOT #6	2022-08-05 11:57
MOT test number	946477820281
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin Both Sides (1.1.13 (a) (ii))	

MOT #5	2022-08-04 08:12
MOT test number	483608957392
Result	X Failed
Advice Nearside Front Nail in tyre	
Advice Rear Brake pad(s) wearing thin Both Sides (1.1.13 (a) (ii))	
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #4	2021-07-12 09:35
MOT test number	593758941065
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2021-07-12 09:04

MOT test number 801457683767

Result

× Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2020-08-05 13:21

MOT test number 743338182876

Result
✓ Passed

Advice Rear unable to inspect rear seatbelts due to seats being folded down and loaded with equipment

Advice Nearside Front Wing mirror backing missing no sharp edges

MOT #1 2019-07-29 10:21

MOT test number 501379679595

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
-------	---------

For how long did the current and previous owner(s) have this FORD? How many owners di Check it in the premium report and see all owner registrations. Download the full report \underline{h}	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-22
Last registration	2023-07-19
Complete history	See info



Registration #1	2016-09-22	27 mi
Registration #2	2019-07-29	5.170 mi
Registration #3	2020-08-05	6.496 mi
Registration #4		71.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	85%
Pedestrian	62%
Safety systems	70%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2137 mm
Height	1845 mm
Length	4818 mm
Kerb weight	1487 kg
Max. allowed weight	2300 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	GG57934

CarCheck.co.uk page 11/11