



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Red
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-05-22
Pictures	31
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-21
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	19
Total items failed	12

MOT #17	2023-05-22 14:09
MOT test number	185819554222
Result	✓ Passed
Next expiry date	2024-05-21

**MOT #16**

2023-05-19 09:41

MOT test number

745959903977

Result**✗ Failed****Minor** Offside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))**Fail** Nearside Front Headlamp insecure (4.1.1 (c))**Minor** Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Emission control equipment obviously defective Failed emissions on Lambda and Co readings (8.2.2.1 (a))**MOT #15**

2022-05-16 10:31

MOT test number

145682268187

Result**✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #14** 2022-05-16 10:30**MOT test number** 804733198573**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #13** 2021-05-22 11:25**MOT test number** 334034291139**Result** ✓ Passed**MOT #12** 2020-07-13 09:36**MOT test number** 176499260392**Result** ✓ Passed**MOT #11** 2019-07-22 08:51**MOT test number** 697255999401**Result** ✓ Passed**MOT #10** 2018-07-25 12:16**MOT test number** 340766937876**Result** ✓ Passed**MOT #9** 2017-05-20 11:02**MOT test number** 272710041899**Result** ✓ Passed**MOT #8** 2017-05-20 11:02**MOT test number** 210636289791**Result** ✗ Failed**Pass with rectification** Driver's door cannot be opened from outside the vehicle (6.2.B.1b)

**MOT #7** 2016-06-02 08:40**MOT test number** 896708930604**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-06-10 12:00**MOT test number** 738931465149**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2015-06-10 12:00**MOT test number** 737031565168**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2014-06-09 16:33**MOT test number** 889370464182**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3	2013-05-30 11:40
MOT test number	207500053415
Result	✓ Passed

MOT #2	2012-05-22 14:29
MOT test number	248603042171
Result	✓ Passed
<div>Notice Front tyres wearing on Outside edge</div>	

MOT #1	2012-05-22 14:29
MOT test number	715903642164
Result	✗ Failed
<div>Pass with rectification Nearside Front Headlamp aim too low (1.8)</div> <div>Pass with rectification Offside Front Headlamp aim too low (1.8)</div> <div>Notice Front tyres wearing on Outside edge</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
21 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	21 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-10
Last registration	2023-05-22
Complete history	See info



Registration #1	2009-06-10	10 mi
Registration #2	2012-05-22	12.678 mi
Registration #3	2013-05-30	18.146 mi
Registration #4	2014-06-09	27.664 mi
Registration #5	2015-06-10	35.348 mi
Registration #6	2016-06-02	44.113 mi
Registration #7	2017-05-20	53.726 mi
Registration #8	2017-05-20	53.726 mi
Registration #9	2018-07-25	59.444 mi
Registration #10	2019-05-22	55.000 mi
Registration #11	2019-05-22	55.000 mi
Registration #12	2019-05-22	55.000 mi
Registration #13	2019-05-22	55.000 mi
Registration #14	2019-05-22	55.000 mi
Registration #15	2019-05-22	55.000 mi
Registration #16	2019-05-22	55.000 mi
Registration #17	2019-05-22	55.000 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1009612