





report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	Black
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-07-07

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-09-14
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	23
Total items failed	12

MOT #16		2023-08-25 15:32
MOT test	number	522518436381
Result		✓ Passed
Next expi	ry date	2024-09-14
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Front Brake pad(s) wearing thin NS&OS (1.1.13 (a) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing NS&OS (5.2.3 (d) (ii))	

MOT #15	2023-08-24 09:36	
MOT test number	273885157653	
Result	× Failed	
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))		
Advice Front Brake pad(s) wearing thin NS&OS (1.1.13 (a) (ii))		
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))		
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Advice Rear Tyre slightly damaged/cracking or perishing NS&OS (5.2.3 (d) (ii))		

CarCheck.co.uk page 3/14



MOT #14 2022-09-07 11:37

MOT test number 635700098020

Result ✓ Passed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake pad(s) wearing thin N/S&O/S (1.1.13 (a) (ii))

MOT #13 2022-09-07 09:55

MOT test number 210840952591

Result X Failed

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake pad(s) wearing thin N/S&O/S (1.1.13 (a) (ii))

Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #12 2021-09-15 13:41

MOT test number 191419867301

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #11 2021-09-14 15:12

MOT test number 501638300291

Result × Failed

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Fail Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 4/14



MOT #10 2021-07-21 12:56

MOT test number 131472746180

MOT #9 2021-07-19 14:29

MOT test number 733022950739

Result X Failed

Fail Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #8 2020-06-06 10:22

MOT test number 404880878629

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2020-05-30 14:31

MOT test number 539303942493

Result X Failed

Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt both outers (6.1.7 (g) (ii))

CarCheck.co.uk page 5/14



 MOT #6
 2019-05-18 09:05

 MOT test number
 839325315656

Result \rightarrow Passed

Advice Anti-roll bar linkage ball joint has slight play fronts (5.3.4 (a) (i))

Advice O/s c/v boot not clipped securely

MOT #5 2018-05-16 11:29

MOT test number 785814284298

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2017-05-18 13:29

MOT test number 723876645868

MOT #3 2016-05-14 11:11

MOT test number 801789076152

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear tyre cracked and perished

MOT #2 2015-05-19 09:57

MOT test number 455819635183

Result

Passed

Notice Rear exhaust hanger snapped not affecting security of exhaust

CarCheck.co.uk page 6/14



MOT #1 2014-05-20 12:16

MOT test number 116360744123

Result ✓ Passed

CarCheck.co.uk page 7/14





Tax & MOT check



✓ MOT

Expires: 14 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-06-27
Last registration	2023-08-25
Complete history	See info



Registration #1	2011-06-27	8 mi
Registration #2	2014-05-20	28.578 mi
Registration #3	2015-05-19	33.696 mi
Registration #4	2016-05-14	41.025 mi
Registration #5	2017-05-18	47.911 mi
Registration #6	2018-05-16	55.216 mi
Registration #7	2019-05-18	60.394 mi
Registration #8	2020-05-30	66.388 mi
Registration #9	2020-06-06	66.388 mi
Registration #3	2020 00 00	
Registration #10	2020 00 00	0.074
		11.777 es
Registration #10		11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11		11.77 m 11.77 m 11.77 m
Registration #10 Registration #11 Registration #12		1.77 m
Registration #10 Registration #11 Registration #12 Registration #13		11.77 es 11.77 es 11.77 es 11.77 es
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 13/14



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1229 kg
Max. allowed weight	1601 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Multi-Point Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5 page	14/14

Number of axles 2

Engine number FSX46458693