



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE PLUS TDI
Colour	Silver
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-05-28
Pictures	50
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-21
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	21
Total items failed	3

MOT #14	2023-06-19 09:00
MOT test number	624948725193
Result	✓ Passed
Next expiry date	2024-06-21
Minor	Anti-roll bar ball joint dust cover severely deteriorated both front upper (5.3.4 (b) (i))

MOT #13	2022-06-17 08:27
MOT test number	959524189543
Result	✓ Passed

MOT #12	2021-06-22 10:51
MOT test number	257158456795
Result	✓ Passed

MOT #11	2021-04-16 09:03
MOT test number	280189935889
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10	2020-04-03 11:44
MOT test number	819767853518
Result	✓ Passed

**MOT #9** 2019-04-10 12:03**MOT test number** 965608459112**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2018-04-05 13:37**MOT test number** 726732542871**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #7** 2017-04-12 15:33**MOT test number** 785444953201**Result** ✓ Passed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #6** 2017-04-12 10:30**MOT test number** 374966987263**Result** ✗ Failed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #5** 2016-04-22 14:32**MOT test number** 899842891411**Result** ✓ Passed

- Advice** Emissions test aborted. Low rev engine. Emissions clear.
- Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Offside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)
- Advice** Rear tyres wearing unevenly inner edges.
- Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Nearside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)

MOT #4 2015-04-17 11:31**MOT test number** 358487305177**Result** ✓ Passed

- Notice** Wiper blades split.
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Offside and nearside rear indicators have 2 LED's out.

MOT #3 2014-04-25 14:00**MOT test number** 405855714131**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2014-04-24 12:42
MOT test number	959894114147
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-04-24 14:58
MOT test number	927964913178
Result	✓ Passed
Notice	Both rear tyres are stepped on inner edge



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-30
Last registration	2023-06-19
Complete history	See info



Registration #1	2010-04-30	29 mi
Registration #2	2013-04-24	37.474 mi
Registration #3	2014-04-24	48.312 mi
Registration #4	2014-04-25	48.312 mi
Registration #5	2015-04-17	61.579 mi
Registration #6	2016-04-22	80.667 mi
Registration #7	2017-04-12	97.765 mi
Registration #8	2017-04-12	97.765 mi
Registration #9	2019-05-20	99.999 mi
Registration #10	2019-05-20	99.999 mi
Registration #11	2019-05-20	99.999 mi
Registration #12	2019-05-20	99.999 mi
Registration #13	2019-05-20	99.999 mi
Registration #14	2019-05-20	99.999 mi
Registration #15	2019-05-20	99.999 mi
Registration #16	2019-05-20	99.999 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1499 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBB 330815