





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	SLK SLK250 CDI BLUEEFFICIENCY AMG SPORT
Colour	Silver
Year of manufacture	2015
Top speed	151 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	500 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history


Entry 1

Date 2022-01-16

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-21
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	14
Total items failed	1

MOT #9	2023-11-22 16:58
MOT test number	610606530849
Result	✓ Passed
Next expiry date	2024-11-21

MOT #8	2022-11-18 12:41
MOT test number	297975230664
Result	✓ Passed

MOT #7		2021-12-23 10:21
MOT test	number	542689356851
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear bumper shows signs of damage	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	())
Advice	Nearside Front Inner arch shows signs of being loose	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2021-12-22 12:08

MOT test number 239313296602

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear bumper shows signs of damage

MAJOR Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

DANGEROUS Nearside Front Inner Tyre tread depth below requirements of 1.6mm edge bold (5.2.3 (e))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Inner arch shows signs of being loose

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm cords exposed (5.2.3 (e))

MOT #5 2021-01-26 12:28

MOT test number 243402643314

Result \(\sqrt{Passed} \)

Advice Front Inner Brake pad(s) wearing thin both worn close to wear indicator (1.1.13 (a) (ii))

MOT #4 2020-01-24 12:11

MOT test number 815108420997

Result

✓ Passed

MOT #3 2019-04-03 13:08

MOT test number 939948019408

Result
✓ Passed

CarCheck.co.uk page 4/12



PN15FHH report date: 2024-03-29

MOT #2 2019-04-03 13:08

MOT test number 661666107898

Result × Failed

Pass with rectification Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #1 2018-02-28 11:48

MOT test number 474405541862

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history

o mile missery	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How r MERCEDES-BENZ have? Check it in the premium report and see all owner registrations report here .	

Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-01
Last registration	2023-11-22
Complete history	See info



Registration #1	2015-03-01	16 mi
Registration #2	2018-02-28	64.812 mi
Registration #3	2019-04-03	49.663 mi
Registration #4	2019-04-03	49.663 mi
Registration #5	2020-01-24	53.241 mi
Registration #6	2021-01-26	54.669 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		0.00 44
Registration #11		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

60225	Air conditionin
60295	
0482	
0501	
0566	
0567	
0569	
iew the complete MERCEDES-BENZ factory list for this	More info >

Dimensions & weight

Width	1810 mm
Height	1301 mm
Length	4134 mm
Wheel base	2430 mm
Kerb weight	1590 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	65198032660976

CarCheck.co.uk page 12/12