



RENAULT

D237JEL

report date: 2024-03-28

General information

Make	RENAULT
Model	R5 GT TURBO
Colour	White
Year of manufacture	1986
Top speed	128 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	135 Nm at 3.750 rpm
Engine capacity	1.397 cc
Cylinders	4
Fuel type	Petrol






Internet history

Entry 2

Date	2021-07-24
Pictures	19
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-05-25
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-11-09
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	41
Total items failed	14

MOT #9	2020-11-10 16:16
MOT test number	402224254072
Result	✓ Passed
Next expiry date	2021-11-09

MOT #8	2020-11-02 14:30
MOT test number	393102012562
Result	✗ Failed
Fail	Offside Rear fog lamp not working (4.5.1 (a) (ii))
Fail	Exhaust emissions carbon monoxide content excessive (8.2.1.2 (b))

MOT #7	2014-04-06 13:21
MOT test number	756996194004
Result	✓ Passed
Notice	Trims fitted to outersills
Notice	Play in offside rear wheel bearing
Notice	Modifications carried out too vehicle
Notice	Oil leaks
Notice	Rear seats missing at time of test

**MOT #6**

2013-03-02 11:35

MOT test number

649031063004

Result

✓ Passed

Notice Corrosion to underside of vehicle**Notice** Sil covers fitted**Notice** Brake pipes corroded**Notice** Oil leak engine**Notice** Fuel pipes corroded**MOT #5**

2013-02-23 09:04

MOT test number

525634953086

Result

✗ Failed

Fail Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**Notice** Sil covers fitted**Notice** Brake pipes corroded**Notice** Oil leak engine**Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**Notice** Fuel pipes corroded**Notice** Corrosion to underside of vehicle



MOT #4

2012-01-24 11:28

MOT test number

899344022036

Result

✓ Passed

- Notice

Handbrake performance very low just in limits.
- Notice

Brake pipes coated.
- Notice

Very slight play in o/s steering rack inner ball joint.
- Notice

Both front wheels very close to inner arches on lock.
- Notice

Front weld repairs heavily coated.
- Notice

Tapley test for brakes due to vehicle being lowered.
- Notice

Floor to sills corroded and weak and heavily coated.
- Notice

Inner wheel arches coated.
- Notice

Very slight play in n/s/f hub.
- Notice

Rear exhaust poorly secured.
- Notice

O/s/r closing sill heavily corroded.

**MOT #3**

2012-01-22 11:46

MOT test number

199342122003

Result**✗ Failed**

- Notice** Rear exhaust poorly secured.
- Notice** O/s/r closing sill heavily corroded.
- Fail** Exhaust emissions carbon monoxide content excessive (7.3.B.1a)
- Notice** Handbrake performance very low just in limits.
- Notice** Brake pipes coated.
- Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Notice** Very slight play in o/s steering rack inner ball joint.
- Notice** Both front wheels very close to inner arches on lock.
- Notice** Front weld repairs heavily coated.
- Notice** Tapley test for brakes due to vehicle being lowered.
- Notice** Floor to sills corroded and weak and heavily coated.
- Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)
- Notice** Inner wheel arches coated.
- Fail** Horn sounds harsh or grating (1.6.2e)
- Notice** Very slight play in n/s/f hub.



MOT #2	2011-12-04 12:33
MOT test number	866568931305
Result	✗ Failed
Fail	Offside Rear Brake pipe excessively corroded (3.6.B.2c)
Fail	Offside Front Tyre fouling a part of the vehicle (4.1.D.2)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Notice	Front to rear fuel pipes heavily corroded
Fail	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)
Notice	Non standard rear silencer fitted and fitted poorly
Fail	Nearside Front Tyre fouling a part of the vehicle (4.1.D.2)
Fail	Nearside Front Wheel insecure (4.2.A.1c)
Notice	Engine oil leaks
Notice	Non standard suspension fitted

MOT #1	2009-09-01 13:49
MOT test number	331864349467
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	1986-08-19
Last registration	2020-11-10
Complete history	See info



Registration #1	1986-08-19	21 mi
Registration #2	2009-09-01	67.792 mi
Registration #3	2011-12-04	67.801 mi
Registration #4	2012-01-22	67.840 mi
Registration #5	2012-01-24	67.846 mi
Registration #6	2013-02-23	70.361 mi
Registration #7	2019-05-29	75.277 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1596 mm
Height	1367 mm
Length	3592 mm

Additional information

Engine number	0019615
---------------	---------