



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO VISIA
Colour	White
Year of manufacture	2011
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-02-05
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-09
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	27
Total items failed	18

MOT #15	2024-01-23 16:28
MOT test number	537985176700
Result	✓ Passed
Next expiry date	2025-02-09
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14	2024-01-18 14:02
MOT test number	383212989230
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Brake fluid close to minimum mark (1.1.10 (d) (ii))
Fail	Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Fail	Horn not working (7.7 (a))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13**

2023-01-25 17:41

MOT test number

747472609253

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2023-01-25 09:15

MOT test number

843005479147

Result

✗ Failed

- Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Horn not working (7.7 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2022-02-10 11:42

MOT test number

284428959542

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Shock absorbers has slight external damage to the casing both (5.3.2 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10

2022-02-08 11:04

MOT test number

522012416232

Result

✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Horn not working (7.7 (a))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear Shock absorbers has slight external damage to the casing both (5.3.2 (b))

**MOT #9** 2021-01-16 11:04**MOT test number** 309304507904**Result** ✓ Passed**MOT #8** 2020-01-27 10:18**MOT test number** 615739560509**Result** ✓ Passed**MOT #7** 2019-01-31 11:17**MOT test number** 321512033538**Result** ✓ Passed**MOT #6** 2018-01-08 12:41**MOT test number** 643832757999**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2018-01-08 12:41**MOT test number** 343389263106**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #4** 2017-01-26 12:40**MOT test number** 247944845892**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #3	2016-01-25 12:51
MOT test number	192583192668
Result	✓ Passed
MOT #2	2015-01-22 10:27
MOT test number	165022825076
Result	✓ Passed
MOT #1	2014-02-06 09:47
MOT test number	156967334440
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-11
Last registration	2024-01-23
Complete history	See info



Registration #1	2011-03-11	22 mi
Registration #2	2014-02-06	26.388 mi
Registration #3	2015-01-22	38.620 mi
Registration #4	2016-01-25	49.972 mi
Registration #5	2017-01-26	61.866 mi
Registration #6	2018-01-08	75.430 mi
Registration #7	2018-01-08	75.430 mi
Registration #8	2019-01-31	88.776 mi
Registration #9	2020-01-27	99.783 mi
Registration #10	2020-01-27	99.783 mi
Registration #11	2020-01-27	99.783 mi
Registration #12	2020-01-27	99.783 mi
Registration #13	2020-01-27	99.783 mi
Registration #14	2020-01-27	99.783 mi
Registration #15	2020-01-27	99.783 mi
Registration #16	2020-01-27	99.783 mi
Registration #17	2020-01-27	99.783 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	133557